

February 10, 1994

(303) 466-3573 FAX: (303) 469-6354



000022040

Mr. Tom Beckman Project Manager EG&G Rocky Flats Project Building 080 Golden, CO 80402-0464

Subject:

SUBCONTRACT PC84017JB ROCKY FLATS SOLAR POND/PONDCRETE PROJECT [WBS 710 - PROJECT MANAGEMENT - HALLIBURTON NUS ROCKY FLATS] PONDCRETE AND SALTCRETE SAMPLING OBSERVATION SUMMARY REPORTS RF-HED-93-0038

Dear Mr. Beckman:

Enclosed are the Pondcrete and Saltcrete Sampling Observation Summary reports recently completed by J. H. Templeton. The Sampling occurred in early 1992, but the completion of the report was delayed until time was made available this year.

Mr. Leon Collins has (through an informal transmittal) already received his copies of both reports, and has been given a copy of the Saltcrete report to forward to Mr. Mike Connell.

This closes out all outstanding activities by J. H. Templeton.

If you have any questions or comments, please contact me.

Sincerely,

HALLIBURTON NUS CORPORATION

Roger A. Hiss

Administrative Manager

RAH/tw

cc: M. Gibson w/o attachments

Attachments:

Memorandum to J. R. Zak January 4, 1994 Pondcrete Sampling

Observations - Summary

Memorandum to J. R. Zak February 9, 1994 Saltc

Observations - Summary

A:\HISS\BECKMAN.001 RF-HED-93-0038



INTEROFFICE MEMORANDUM

DATE:

February 9, 1994

FILE NO.

765.9

TO:

J. R. Zak

FROM:

J. H. Templeton

SUBJECT:

EG&G Rocky Flats

Solar Pond/Pondcrete Stabilization Project

B&R Job No. JR-1198

REFERENCE:

Saltcrete Sampling Observations - Summary

Attached (see below) is all the documentation from the Saltcrete waste form sampling, performed between January 7 and 30, 1992. Sampling was performed based upon the Pondcrete/Saltcrete Sampling and Analysis Plan, Pondcrete/Saltcrete Sampling Standard Operating Procedure, and all upper tier documents (i.e. HNUS Health and Safety Plan, HNUS Quality Assurance Plan). Halliburton NUS used a statistical analysis to select which blocks would be sampled, based on the storage method (number of stand-along triwalls, number of triwalls in metal containers, and the number of saltcrete halfcrates), and the placement in each waste storage area (stack #, tent #, pad #). The statistics and selection were not based on production number or accumulation date. During the time period stated above 40 stand-alone triwalls, 8 triwalls in metal containers, and 12 halfcrates, for a total of 60 saltcrete blocks were sampled. The block sampling order was random.

The following summary table contains most of the pertinent sampling data, and is intended to draw comparisons between samples, not the replace the observations data sheets. After all of the data was entered into the summary table format it was sorted based on accumulation date and triwall number.

Examining the ordered block numbers and accumulation dates indicates that for some of the triwalls in metals, either the accumulation date of the metal (instead of the triwall) was noted (e.g. #3326, #3257, #3287), or a wrong date was recorded (e.g. #4099). Some of the stand alone triwalls (#3018, #2410, #4440, #4436, #4634) also have conflicting accumulation dates indicating either the block was assigned a number outside the numerically increasing sequence, or the accumulation dates were assigned at some time after production. Finally, triwall #13524, may possibly be #3524 as this would make both the numerical sequence and the accumulation dates agree.

The data in the summary table was sorted and analyzed for similarities by the following categories:

I DATE/BLOCK NUMBER/CONTAINER TYPE

<u>Stand-Alone triwalls</u> - No correlation or similarities are observed through sequential block number and date. Also, by comparing observations for blocks with the same accumulation date (2410-3125-3137) or within a 2 to 14 day range of accumulation dates (3440-3456-13524-3653;

3817-3831-3873-3874-3882-3886; 4059-4031-4084; 4440-4436-4634) indicates either a wide variation in the feed material which could not be averaged out by the stabilization formula, or poor control in the addition of the formula components.

<u>Triwalls-In-Metals</u> - Typically stand-along triwalls were placed in metal containers due to the triwall box leaking, sagging, breaking open or the material inside not being hard enough to support the weight of one or more blocks being stacked on top of it. The following comparisons could be made.

- 8 of the 48 triwalls sampled (17%) were in metal containers.
 - 7 of 8 (88%) had orange discolored liners, and 1 of 8 had rust discoloration.
 - 7 of 8 (88%) had liners which were brittle and torn.
- 5 of 8 (62%) had penetrometer readings of 0.
- 7 of 8 (88%) were grey or white in color.
- 6 of 8 (75%) were dry or had slight moisture.
- 5 of 8 (62%) were relatively soft throughout.

<u>Halfcrates</u> - The 12 halfcrates which were sampled were produced between 6/89 and 9/91, and the following comparisons could be made.

- Nearly all liners noted were clear, flexible, and intact.
- All blocks (100%) showed penetrometer readings > 4.5.
- 9 of 12 (75%) were grey in color, and all 12 were of a shade of grey.
- All 12 (100%) were dry.
- 10 of 12 (83%) were very hard, and none were soft.
- 9 of 12 (75%) broke into large chips or slabs when sampled.

II COMPARISON BY LINER CHARACTERISTICS

During sampling the liner condition was noted for:

Color C - Clear (no discoloration)

O - Orange discoloration

R - Rust discoloration

Flexibility F - Flexible

B - Brittle

Integrity I - Intact

T - Torn

- 20 Blocks (33%) were noted to have clear liners.

 Of these, 14 (70%) were dry, 13 (65%) were hard or very hard throughout, and 16 (80%) had a grey-shade coloring.
- 26 Blocks (43%) were noted to have flexible liners.

 Of these, 14 (54%) were dry, 14 (54%) were hard or very hard throughout, and 20 (77%) had a grey-shade coloring.

- 29 Blocks (48%) were noted to have intact liners.

 Of these, 15 (52%) blocks were dry, 18 (62%) were hard or very hard throughout, and 23 (79%) had a grey-shade coloring.
- 30 (50%) of the blocks were noted to have orange-discolored liners. Of these, 23 blocks (77%) had a grey color.
- 18 Blocks (30%) were noted to have brittle liners. Of these, 15 (83%) had a grey color.
- 12 Blocks (20%) were noted to have torn liners.

 Of these, 6 blocks (50%) were dry, and 9 (75%) had a grey-shade coloring.
- 5 Blocks (8%) were noted to have rust discolored liners.
 Of these, 4 (80%) were dry or contained slight moisture, 3 (60%) were of medium hardness (1 hard, 1 very hard), and all (100%) had a grey-shade coloring.

A clear, flexible, intact liner was considered to be in like-new condition. A liner with orange discoloration could still flexible and intact, but a brittle liner was always discolored, and a torn liner was always discolored and nearly always brittle. A mildly discolored liner, i.e. light orange or light rust, tended to be more flexible than a darker discolored liner, i.e. dark orange, or red. The darker the discoloration, the more brittle the liner, and the more likely it was to be torn.

III MATERIAL COLOR

- 29 Blocks (48%) were grey colored material.

 Of these, 22 (76%) were dry or had slight moisture, 14 (48%) had penetrometer readings

 > 4.5, 13 (45%) were hard or very hard throughout, and 12 (41%) had a medium hardness throughout.
- 15 Blocks (25%) were light grey or grey-white in color. Of these, 9 (60%) were dry or had slight moisture, 7 (47%) were hard or very hard throughout, and 7 (47%) had a medium hardness throughout.
- 1 Block (2%) was a dark-grey colored material. It had a white crust across the top, had penetrometer readings > 4.5, was dry and very hard. The material surface had voids and looked like pumice.
- 7 Blocks (12%) had white or off-white colored material, of mixed observable characteristics.
- 6 Blocks (10%) were a brown shade (Brown-Grey, Brown-Rust, Grey-tan, Light brown, and Tan).
 Of these, 5 blocks (83%) were dry or of slight moisture, 3 (50%) were hard or very hard, 3 (50%) had penetrometer readings < 1.25, and 4 (67%) had orange liners, 3 of which (50%) were also brittle and torn.

• 2 Blocks (3%) were a green-shade (grey-green, tan-green). Both blocks had orange discolored liners and medium penetrometer readings of 2.5 - 3.0. The blocks were soft to medium in apparent hardness throughout.

IV WETNESS OF MATERIAL

- 29 Blocks (48%) were dry.
 Of these, 18 blocks (62%) had penetrometer readings of 4.0 to > 4.5, 23 blocks (79%) were grey colored material, and 22 blocks (76%) were hard or very hard.
- 14 Blocks (23%) had slight moisture.
 10 of these blocks (71%) had an orange discolored liner.
- 10 Blocks (17%) had moist material.

 Of these, 9 blocks (90%) were grey-shaded material, 7 blocks (70%) were medium in hardness, and 6 blocks (60%) had orange discolored liners.
- 2 Blocks had damp material. Both liners were orange, the material was grey, and the blocks were hard or very hard.
- 1 Block was wet inside. The penetrometer readings were all zero, the liner was orange, the material was grey-tan in color, was like a soft sand or mud, was sticky, and molded together when pressed by hand.
- None of the blocks sampled showed free moisture.

V APPARENT HARDNESS

Apparent hardness was estimated by the ease or difficulty encountered when inserting the Shelby tube through the block.

- 16 Blocks (27%) were very hard.

 Of these, 9 blocks (56%) had clear liners, 15 blocks (94%) had penetrometer readings

 > 4.5, 15 blocks (94%) had grey colored material, 13 blocks (81%) were dry, and 12 blocks (75%) created a dust-slab mixture when sampled.
- 14 Blocks (23%) were hard.
 Of these, 11 blocks (79%) were grey, and 9 blocks (64%) were dry.
- 21 Blocks (35%) were of medium hardness.

 Of these, 18 blocks (86%) were grey in color, and 12 blocks (57%) were dry or had slight moisture.
- 9 Blocks (15%) were soft.
 Of these, 8 blocks (89%) had orange liners, 7 blocks (78%) had penetrometer readings of 0, 5 blocks (56%) were a grey-shade, and 6 blocks (67%) were dry or had slight moisture. All of the blocks yielded fine powder to sandy material for the sample.

VI MISCELLANEOUS OBSERVATIONS

Ammonia Smell - Three of the triwall blocks expelled an ammonia smell immediately upon opening. An additional triwall block did not begin to smell until sampled to a depth of approximately 10 inches. All of the triwalls were grey and had no voids. The blocks were of varying wetness, and hardness. Two of the four blocks were expanded.

Expanded - Five of the triwall blocks expanded sufficiently to either break the liner or the sides of the triwall box. All five blocks had orange liners with a mix of flexibility and integrity. Four of the five blocks had penetrometer readings less than 1.5, while the fifth block had penetrometer readings all > 4.5. All had dust or fine sand on the top of the block, and a mix of color, wetness and apparent hardness. Two of the blocks exhibited an ammonia smell, and two molded together when squeezed by hand.

<u>Stickiness</u> - Six of the triwall blocks, one of which was in a metal container, showed some degree of stickiness. All of the blocks were grey to grey-white in color, and tended to be soft to medium in apparent hardness.

<u>Pumice-Like/Air-Bubbled</u> - One of the blocks had an air-bubbled surface, and three had the appearance of pumice. Two of the blocks were triwalls and two were halfcrates. Three of the blocks had clear liners, and all four had intact liners. All four blocks were very hard, and grey to dark grey in color. The three pumice-like blocks were dry inside and the air-bubbled block was damp inside.

Work Softening - In sampling three of the blocks, work softening was observed, that is, the material was dry and hard until work was applied (e.g. drill compression, hammering, pressing, chiseling), forcing moisture out of the material, making it damp, soft, and pliable. It was only noticed in three blocks to which a great amount of force was used in sampling. It is possible, and likely that many of the dry, hard blocks sampled would also have exhibited work softening under similar sampling conditions. All three blocks had penetrometer readings > 4.5, were grey to dark grey in color, dry or had slight moisture, hard or very hard, and broke into slabs and chips. The material could not be broken or molded by hand, unless first worked into a soft mass.

<u>Clay-Like Texture</u> - Ten of the blocks sampled had a clay-like appearance or clay-like texture. Of these, 6 blocks had liners which were flexible and intact, 5 blocks had penetrometer readings > 4.5, and 7 blocks were grey in color.

Molds Together When Pressed - 17 of the triwalls, one of which was in a metal container, molded together when pressed by hand. Of these, 13 had a liner with an orange discoloration, most of the blocks was slight in moisture to moist, and most were soft to medium in apparent hardness. Only the dust or sand particles would mold when pressed together.

<u>Particles on Top of the Blocks</u> - 18 blocks had loose dust, flakes or sand particles on top of the when opened. Three of these blocks were halfcrates.

11 of the 15 triwalls (73%) had orange liners, 11 of the 15 triwalls were dry or had slight moisture, and 11 of 15 triwalls were medium to very hard.

All three halfcrates had particles on top, had a grey-shade coloring, were dry, hard or very hard, and broke into dust and slabs when sampled. Like all of the halfcrates, the penetrometer readings for all three blocks were > 4.5.

<u>Crust on Top of Block</u> - Three triwalls, one of which was in metal container, and 3 halfcrates had white or yellow salt-like crusts on top of the blocks. The three triwalls all had orange liners, and two out of three were brittle and torn. All three halfcrate had liners which were clear, and two of them were noted to be clear and flexible. Five of the blocks had a grey shade coloring, and the remaining block was white. Five of the blocks were dry or had slight moisture. Four of the blocks were hard or very hard, and none of the blocks were soft. The three halfcrates were produced between 12/90 and 5/91.

VI CONCLUSIONS

The above analyses have tried to indicate possible comparisons between saltcrete blocks to determine what may have been factors in, or evidence of, block stability or failure. An alternate method of analysis would be to identify those characteristics of "good" saltcrete blocks, and then examine which blocks have those characteristics. I identified and prioritized those physical characteristics which I felt would make a "good" pozzolan-based stabilized waste form, with 1 having the highest priority and 7 having the lowest.

- 1 Apparent Hardness of Hard or Very Hard A pozzolan-based stabilized waste form which is mixed in the adequate quantities to provide solidification and stabilization should be "hard." All blocks noted as Hard or Very Hard were initially retained.
- 2 Dry or having Slight moisture A pozzolan-based stabilized waste form should be fully hydrated without excess moisture. Additionally, NTS acceptance criteria include a maximum free water content. All Hard or Very Hard blocks which were dry or had slight moisture were retained.
- 3 The liner should be Flexible and Intact If the liner is brittle or torn open the material can begin to degrade the container it is stored in, resulting in eventual spillage. All Hard or Very Hard blocks which were dry or had little moisture and had brittle or torn liners were discarded.

The remaining blocks are shown in the attached table, Summary of Saltcrete Sampling Observations - Table of Conclusions.

The next items to consider but of lesser importance, and identified in the table by shading, were:

- 4 Homogeneity A pozzolan-based stabilized waste form should be homogeneous throughout, meaning crusts, spots, and swirls would be undesirable;
- 5 Particulates The NTS acceptance criteria places a limit on the quantity of fines which may be included in a mixed waste package, the maximum allowable limit is actually quite high;
- 6 Clay Clay-like material indicates an unsolidified pozzolan-based waste form and is thus undesirable;
- <u>7 Penetrometer readings</u> This is only a relative indicator of the hardness of the top of the block and thus is the lowest indicator.

The Table of Conclusions shows that there were Triwall blocks produced between December 26, 1986 through December 11, 1988 which met the first three "good" block criteria, with no common production dates.

The Table also shows that all but one halfcrate block met the three primary "good" block criteria. This may be due to the fact that the halfcrate liners are merely folded over the waste, allowing easier escape of moisture and a drier, harder waste form. It is also likely that the techniques involved or stabilization formula used to produce the saltcrete halfcrates are what resulted in their apparent successful stabilization.

ATTACHMENTS: - Summary of Saltcrete Sampling Observations - Table including all blocks sampled

- Summary of Saltcrete Sampling Observations Table of Conclusions
- Saltcrete Metal Sampling, January 7, 1992 (1 Sheet)
- Saltcrete Triwall Sampling, January 13-16, 1992 (7 Sheet)
- Saltcrete Triwall and Metal Sampling, January 20-21, 1992 (5 Sheet)
- Saltcrete Halfcrate and Metal Sampling, January 27-30, 1992 (5 Sheet)
- Saltcrete Sample Data Sheets, from Sample SC-01408-M through SC-605xx-M

cc: W. C. Henderson/B&R Project File

- T. A. Bittner/R. Hiss
- L. A. Collins/M. Connell

SUMMARY OF SALTCRETE SAMPLING OBSERVATIONS

BLOCKS 2 through 40, and 42 are in triwall containers BLOCKS 1, 41, 43, 44, 57 - 60 are in metal containers BLOCKS 45 through 56 are in wooden halfcrate containers

SUMMARY OF SALTCRETE SAMPLING OBSERVATIONS

BLOCKS 2 through 40, and 42 are in triwall containers
BLOCKS 1, 41, 43, 44, 57 - 80 are in metal containers
BLOCKS 45 through 58 are in wooden halfcrate containers

OTHER LINER PENET. INFO COND* READIN
╁
2.0-4.5
>4.5
0 >4.5 DAMP CLAY
OB 4.0->4.5 WHITE STRE AKS
CFI >4.5 LIKE PUMICE
IN METAL RBT 4.0->4.5 PRESSED FINES
M00818 OBT 0 CRUST
1.0-4.5 WHITE PARTICLES
OBT
OFI 2.0-4.5
0.8 3.0
RB 2.0-3.5
OF! >45
RI >45
•
GF1 > 4.5
: 5
× × × × × × × × × × × × × × × × × ×
%CRATE CFI > 4.5 CHIPS/CLAY - LIKE
>4.5
\$ ** \$
GFI >45
V2CRATE CFI >4.5 1/16" WHITE CR UST
+CRATE C >4.5 WHITE CRUST
V2CRATE CFI >4.5 1/4" WHITE CR UST
FICRATE >4.5 NOT DUSTY

SUMMARY OF SALTCRETE SAMPLING OBSERVATIONS TABLE OF CONCLUSIONS

											ŀ	
SMENCS		ACCUM	OTHER	LINER	PENET.	MATERIAL			APPARENT	PAR TICLE		
D MILLIMING	300	DATE	CHNI	COND	READING	APPEARANCE	COLOR	WETNES	HAR DNESS	SIZE	VOIDS	OBSERVATIONS
OKUER	DECCA											
)			7 7 7		GREY	SLIGHT	HARD	MIX	NO	CLAY - LIKE TEXTURE
æ.	2539	977198	<u> </u>	5 (}	CONTINUE CLAB D	WHITE	!	V. HARD	LARGE	ON	DOES NOT CRUSH, CRUMBLE, MOLD
30	2793	870405	i	5	×4.5	WHILE RAN D				<u> </u>		CHINKS ARE HAR D
33	3018	870528	1	F	4.0-4.5	WHITE SPOTS	GREY	DRY	HAKD	Y IW		
	3440	870920	!	5	2.5-4.5	SANDY	GREY-WHT	DRY	HARD	SAND		
;	3882	880518	1	0	>4.5	DRIED CLAY	GREY	SLIGHT	HARD	!	ON ON	CAN'T BREAK, CAN'T MOLD, WORK SOFTENS
} ,	3808	1	1	5	×4.5	!	GREY WHT	DRY	HARD	FLAKY	0N	YELLOW SPOTS
^ <i>;</i>	1084	860707	;	3	>4.5	LIKE PUMICE	GREY	DRY	V. HARD	3-4"	YES	VERY SOLID, HOMOGENEOUS
;	4160	880805	!	l }	1.0-4.5	WHITE PARTICLES	GREY	DRY	HARD	DUST	<u> </u>	CRUMBLY
3 3	51.7	880809	!	OFI	2.0-4.5	-	OFF WHT	DRY	HARD	FINDSAND	0 2	MOLDS TO GETHER
9 %	4634	881211	1	OFI	>4.5	WHITE SWIRLS	GREY		HARD	DUST~3"	0 Z	AMOR PHOUS INSIDE
۶ ۰		;	1	•	>4.5	1	GREY WHT	DRY	HARD	POWDER	o N	1
, E	HO-776-A-5441		14CRATE	~	>4.5	FINE PARTICLES	GREY	DRY	HARD	DUST-SLABS	0 Z	
25	776-A-6189		VCRATE	Ę.	>4.5	-	GREY	DRY	V.HARD	DUST-CHUNKS		CAN'T BREAK/CR UMBLY
: ¥	804-776-A-5560) VACRATE	F	> 4.5	DUSTY	GREY	DRY	V. HARD	DUST-SLABS	9 2	WOR K SOFTENS
; ¥	748-00032			!	>4.5	WOR K DAR KENS	GREY	DRY	V. HARD	DUST-SLABS	0 N	CAN'T BREAK, CAN'T MOLD
2,5	H00264	900-108	VCR ATE	1	 >4.5	MOSTLY FINES	BRN-GREY	DRY	V.HARD	DUST-SLABS	0 N	CAN"T BREAK
: 3	H03211	901218		<u>P</u>	>4.5	1/16" WHITE OR UST	GREY	DRY	V. HARD	1	0 N	THIN SLATE - LIKE CHIPS
2 4	H03453	910405			> 4.5	WHITE CRUST	D. GREY	DRY	V. HARD	MIX	o z	PUMIŒ 1/8" HOLES, WORK SOFTENS
	H03509	910509		ਦ	× 4.5	1/4" WHITE OR UST	GREY	DRY	V.HARD	CHIPS	0 Z	POR OUS, PUMICE
	748-00466	910930		!	× 45	NOT DUSTY	GREY	DRY	V.HARD	LAR GE CHIFS	l	CAN'T BREAK
. 9	H03202	,	VCRATE	<u>5</u>	>4.5	1	L. GREY	DRY	V. HARD	1-5"	o z	
20	H00198	,	15CRATE	G-I	>4.5	CHIPS/CLAY-LIKE	GREY	DRY	V. HARD	1-5"	ON	PAGE 1 OF

SALTCRETE METAL SAMPLING

January 7, 1992

1. Triwall # 04104 (HNUS # SC-01408-M) Dated 7/21/88 Taken from Metal M00818

- The PVC bag is discolored light orange to orange. It is brittle and broken.
- The top of the saltcrete block is grey-cream colored with white swirls and yellow patches.
- The grey cream areas are soft, penetrometer reading of zero.
- The white swirls are only a crust on top of the soft grey-cream material with a penetrometer reading of >4.5. The crust is only about 1/16" thick and can be peeled back. Close examination shows clear square salt crystals adhered to an off-color smooth surface.
- The yellow patches show a penetrometer reading of >4.5
- The undisturbed sample was taken using a Shelby tube and had to be pounded in using a large sledge hammer (very hard) and removed using a forklift.
- The core hole is smooth and a medium grey color, with no free liquid.
- The jar samples were taken using a small shovel.
- The top is a hard crust which the shovel cuts through easily. The crust is grey-white, and crumbles easily.
- A lump approximately 1" in size was observed, but all lumps seemed to crumble easily when squeezed.
- While the sample appears dry and dusty, it seems to still contain some moisture.
- The material feels slick, not gritty.
- Sample was taken to about 12" deep and all of the material looked very consistent.
- When the material is crumbled it is light grey to white and dry in appearance.
- When the material is cut it discolors to a medium grey color and looks slightly moist.
- When a handful of fines are squeezed they hold together as one mass.
- When a handful of fines are scattered they fall readily and do not dust.

SALTCRETE TRIWALL SAMPLING

January 13-16, 1992

2. Triwall # 03873 (HNUS # SC-02408-T) Dated 5/17/88

- The liner is clear with some orange discoloration on one side, and has no tears or breakage.
- The material on top is crumbly, dry, and does not stick to the liner.
- Penetrometer readings: 2.5, 4.5, 4.5, 4.5, 4.5.
- The Shelby tube was hammered in with a small sledgehammer, the forklift was used to pull it out.
- The Shelby tube removed cleanly. The hole was smooth with no voids, no rocks, and no free liquid.
- When squeezed, the material shatters into dusty, small particulates.
- The material was sampled using a chisel and rubber mallet.
- The material is grey and does not stick together.

3. Triwall #03912 (HNUS # SC-03408-T) Dated 5/22/88

- Most of liner is in good condition with some orange discoloration and cracked areas.
- Very little material is adhering to liner.
- The material is grey-off white.
- Penetrometer readings: Center >4.5, Corners 2.0, 2.5, 2.5, 4.0.
- The Shelby tube was hammered in using the large sledgehammer, and a hammer and chisel were used to take the remaining sample.
- The Shelby tube went all the way to the bottom of the block. The hole is smooth all the way to the bottom, with no voids and no free liquid.
- The material presses into a ball, but then with additional pressure breaks back into sand size granules.

4. Triwall #03874 (HNUS # SC-04408-T) Dated 5/17/88

- The liner is visibly orange and yellow, and very rigid. It is cracked in various places and some dry material is lightly adhered to the liner.
- The material is grey-off white.
- There is some particulates on top of the block.
- Penetrometer readings: All > 4.5.
- A small sledgehammer was used to push the Shelby tube all the way to the bottom of the block. The bottom 2 to 3 inches of sample fell out of the block during removal. The hole is smooth with no voids and no free water.
- The material can be easily ground to a medium-sized sand texture.
- With pressure, the material molds together and exhibits some moisture.
- The material is not sticky.

5. Triwall #03898 (HNUS # SC-05410-T) No date

- The liner is clear, flexible, and has no tears.
- The material on top of the block is grey-off white.
- Penetrometer readings: All > 4.5.
- The Shelby tube could only be pounded in ¼ of the way. The hole is smooth with no voids and no free liquid.
- The material is grey-white, dry and flaky, and has some yellow spots.

6. Triwall #? (HNUS # SC-06410-T) No date

- The liner is mostly clear with some orange discolored areas.
- Penetrometer readings: All > 4.5.
- The Shelby tube could only be pounded in about 9" using both the sledgehammer and dropping the forklift forks on it. The hole has no voids and no free water.
- The material is a white-grey dry powder.

7. Triwall #04226 (HNUS # SC-07408-T) Dated 8/6/88

- The liner is orange where in contact with the material. The liner is stiff and breaks easily. No material is stuck to it. There is a fine dust on top of the triwall.
- Penetrometer readings: 3.5, 2.0, 3.0, 3.0, 2.5.
- The Shelby tube pushed in ¼ of the way using the fork truck and was hammered in to ¾ of the way (total) using the sledgehammer. The tube was removed using the forklift. The hole is smooth with no voids, no rocks, and no free liquid.
- The material is light brown and crumbles easily, but individual particles are dry and hard.

8. Triwall #13524 (HNUS # SC-08408-T) Dated 9/28/87

- The box is bulged, but not broken open.
- The liner is orange and stiff, but does not tear. Some material is on the liner, but is dry and readily falls off.
- There is a strong ammonia smell.
- Penetrometer readings: 1.5, 0, 1.0, 1.5, 1.5.
- The Shelby tube was hammered % of the way into the block. The block is very hard. The hole is smooth with no voids, no rocks, and no free liquid.
- A chisel and shovel were used for the remaining sampling.
- The material is grey, crumbles into a powder with pressure, and shows a slight sticking together.

9. Triwall # ? (HNUS # SC-09408-T) Dated 7/4/88

- The box is split open on one corner.
- The liner is orange, with no tears except on the split corner. The material is not adhered to the liner.
- The triwall top is light grey marbled with white streaks.
- There is a strong ammonia smell.
- Penetrometer readings: All > 4.5.
- The Shelby tube was hammered into the triwall about ¾ of the way very hard. The hole is smooth with no voids, no rocks, and no free liquid.
- The material is light grey, dry, and flaky, crumbles with pressure, and does not stick together. The material feels gritty.

10. Triwall #04031 (HNUS # SC-10408-T) Dated 7/7/88

- The liner is orange and brittle with very little material stuck to it. Some dry flakes are on top of the triwall.
- The triwall is grey with white streaks.
- Penetrometer readings: Center 4.0, Corners: 4.5, 4.5, >4.5, >4.5.
- The Shelby tube was pounded into the block using a sledgehammer. The hole is smooth with no voids and no free liquid.

10. Triwall #04031 (HNUS # SC-10408-T) Dated 7/7/88, continued

- When large particles are squeezed together they do not crumble nor mold together. However, when the sandy-looking material was squeezed it molded into a ball.
- Most of the sample was coarse-sand size.

11. Triwall #04059 (HNUS # SC-11408-T) Dated 7/4/88

- The liner is orange to dark orange in color, with no tears and very little material stuck to it.
- The top of the block is light grey with white streaks, and has some dry particulates.
- Penetrometer readings: All > 4.5
- The Shelby tube was inserted using a sledgehammer. The hole is smooth, but looks damp, like wet clay, with no voids and no free liquid.
- The material breaks into palm sized pieces which do not mold back together with pressure.

12. Triwall #04436 (HNUS # SC-12408-T) Dated 10/10/88

- The liner is orange with dark orange, almost black, spots.
- The top of the block is light grey with small paper-like flakes.
- Penetrometer readings: All > 5.
- The Shelby tube was inserted using a sledgehammer and the forklift was used to remove it. The tube went completely through block. The hole looks like slippery damp clay, with no voids and no free liquid.
- The material easily crumbles, but molds together when squeezed. The particles have clay like properties, and the material is slightly sticky.

13. Triwall #03831 (HNUS # SC-13408-T) Dated 5/13/88

- The liner is in good condition with some orange-yellow areas. A dusty material is adhered to the liner.
- The top of the block is white with light grey splotches, and has some loose particulates.
- Penetrometer readings: All > 4.5.
- The Shelby tube was inserted all the way through the block using a sledgehammer. The hole has no voids and no free liquid.
- The material breaks into a medium-sized sand and pea gravel.
- The large pieces do not press together when squeezed.
- The sand holds together when squeezed and acts like a heavy, wet clay.
- The sledgehammer broke off the handle of Shelby tube when pushing it into the triwall.

14. Triwall #03937 (HNUS # SC-14408-T) Dated 6/20/88

- The liner is yellowing, but in good shape, with some dusty material adhered to it.
- The top of the block is off-white with some light grey areas. Looks like a slightly damp dense clay.
- Penetrometer readings: All 4.5.
- The Shelby tube was inserted using a sledgehammer. The hole is smooth and slightly damp, with no voids and no free water.
- The material easily presses together and is slightly sticky.
- The particles range from medium sand, to pea gravel (predominant) to golf ball size.

15. Triwall #04174 (HNUS # SC-15408-T) Dated 8/17/88

- The liner is in good condition with some particulates stuck to it.
- The top of the block is a brown/rust color, with dry particulates scattered everywhere.
- Penetrometer readings: All 0.
- The Shelby tube was inserted with a sledgehammer. The material is dry and has no free liquid.
- The material is like a medium to fine sand and can be pressed together into a loose ball.

16. Triwall #04162 (HNUS # SC-16408-T) Dated 8/9/88

- The liner is in good condition and flexible, with some orange spots.
- The top of the block is white and off-white (yellowish) and dusty.
- Penetrometer readings: Center 4.5, corners 2.0, 3.0, 3.5, 4.0.
- The Shelby tube was inserted with difficulty, using a sledgehammer. The hole is smooth with no voids and no free water.
- The particles easily crumble to a fine sand which feels gritty and dry.
- The material does press together into a ball.

17. Triwall #02828 (HNUS # SC-17408-T) Dated 4/10/87

- The liner is yellow orange, stiff, but not brittle. There are splits in the liner apparently due to the block expanding.
- The top of the block looks like white/grey fine sand.
- Penetrometer readings: All 0 (soft fine sand).
- The Shelby tube was inserted using the sledgehammer. The hole was smooth and damp looking with no voids and no free liquid.
- The larger pieces would not squeeze together, but the fine sand pressed easily into a ball.

18. Triwall #02225 (HNUS # SC-185XX-T) Dated 10/13/86

- The liner was slightly orange/yellow, and overall in good shape with some dusty material stuck to it.
- The top of the block is grey.
- Penetrometer readings: Center 3.5, corners 1.0, 3.0, 1.5, 1.0.
- The Shelby tube was inserted with the sledgehammer. The hole is smooth and clean with no voids and no free liquid.
- Particles are medium to fine sand-size and press together into a ball. It is not very sticky.

19. Triwall #03011 (HNUS # SC-195XX-T) Dated 5/22/87

- The liner is yellowing, but is in good shape with some particulates stuck to it.
- The top of the block is white to off-yellow and looks like fine beach sand.
- Penetrometer readings: All 1.0.
- The Shelby tube was inserted with a sledgehammer. The hole is smooth with no voids and no free liquid.
- The material breaks apart easily, while still sticking together like damp sand.

20. Triwall #02585 (HNUS # SC-205XX-T) Dated 2/2/87

- The liner is rust colored on the inside and is semi opaque. A thin layer of flaky dried material is stuck on liner. Water is present on the outside of the liner.
- The top of the block looks grey, clay-like and semi-plastic.
- There is a strong ammonia odor.
- Penetrometer readings: 2.0, 2.0, 2.0, 1.5, 1.75.
- The Shelby tube was inserted using a sledgehammer and forklift. The hole is smooth with no stratification, no voids, and no free water.
- The material is workable and sticks together, but is not messy, dry, or dusty.
- The material crumbles into approximately 1 inch pieces and is slightly sticky.

21. Triwall #02237 (HNUS # SC-215XX-T) Dated 12/23/86

- The liner is intact and rust colored on the inside. There are no liquids on the outside of the liner.
- The top of the block is a greyish color.
- There is a strong ammonia odor.
- Penetrometer readings: 2.5, 2.5, 3.0, 3.0, 4.0.
- The Shelby tube was inserted and removed using the forklift. The hole is smooth with no voids and no free liquid.
- The material is clay-like, yet semi-dry and crumbly. It is not sticky, gritty, hard, or sandy.

22. Triwall #03137 (HNUS # SC-225XX-T) Dated 7/10/87

- The liner is clear and clean with nothing adhered to it.
- The top of the block is off-white and the material on top is fine, dry and dusty, with a soft-flour-like texture.
- Penetrometer readings: All 0.
- The forklift was used to insert and remove the Shelby tube. The hole collapsed when the tube was removed, but no voids and no free water were apparent.
- The material is a white, fine, soft powder.

23. Triwall #03456 (HNUS # SC-23408-T) Dated 9/22/87

- The liner is intact, clear, and no material is stuck to it.
- The top of the block is grey.
- Penetrometer readings: 1.5, 1.5, 1.5, 2.0, 1.75.
- The Shelby tube was inserted using the forklift and a sledgehammer. The hole is smooth and homogeneous and has no voids and no free liquid.
- The material is a grey, soft powder, like flour, but semi-damp, and crumbles easily.

24. Triwall #04084 (HNUS # SC-24408-T) Dated 7/7/88

- The liner is intact with a clear, flaky-hard residue adhered to it.
- The top of the block is grey, very hard, and looks like pumice.
- Penetrometer readings: All > 4.5.
- The Shelby tube sample could not be taken too hard, the tube bent.
- Used a hammer and chisel to sample in 3 to 4" thick ridges.
- The material is very solid, very hard, homogeneous, and cannot be crumbled or broken by hand.
- No free water was apparent.

25. Triwall #02549 (HNUS # SC-25408-T) Dated 1/2/87

- The liner is orange-yellow with some particles adhered to it.
- The top of the block is a tan/green color with a sandy texture and white particulates.
- Penetrometer readings: All 2.5.
- The Shelby tube went all the way to the bottom of the triwall. The hole is smooth and wet in appearance with no voids and no free liquid.
- The material crumbles, but is easily pressed together. Overall the material is damp.

26. Triwall #03653 (HNUS # SC-26408-T) Dated 10/29/87

- The liner is slightly yellowed, but in good condition, with material adhered to it.
- The top of the block is white with loose particulates.
- Penetrometer readings: center: 4.0, corners 4.5, 4.5, >4.5, 4.5.
- The Shelby tube sample was taken and the hole showed no voids and no free liquid, but the walls looked damp.
- The material presses easily together and is sticky. Used a hammer and chisel to take the sample.
- The material is like both a sand and a hard dense clay.

27. Triwall #03125 (HNUS # SC-275XX-T) Dated 7/10/87

- The liner is orange and split in various areas.
- The block seems to have expanded considerably.
- The top of the block is white/off-white, and dusty.
- Penetrometer readings: All 0.
- The Shelby tube sample was taken easily, and the remaining sample scooped out with shovels. The hole looks like sand, but with no large voids and no free water.
- The material is very sandy and soft, and presses easily together.

28. Triwall # ? (HNUS # SC-285XX-T) Dated 6/25/89

- The liner is orange.
- The top of the block is white, like soft sand.
- Penetrometer readings: All 0.
- The Shelby tube sample was taken by hand. The hole is smooth, with no voids and no free liquid.
- The interior of the block is grey/tan, and looks like a mushy mud/clay.
- The material presses together easily and is very sticky.

29. Triwall #04160 (HNUS # SC-29408-T) Dated 8/5/88

- The top of the block is light grey with white particulates.
- Penetrometer readings: 4.5, corners: 3.5, 2.0, 1.0, 2.5.
- The Shelby tube was difficult to insert. The hole is smooth and dry, with no voids and no free liquid.
- The material is light grey, crumbly, and presses together only momentarily.
- Overall, it is dry and dusty, not sticky.

30. Triwall #02793 (HNUS # SC-30408-T) Dated 4/5/87

- The liner is slightly yellowed, and intact.
- The top of the block is white and rock hard.
- Penetrometer readings: All > 4.5.
- Only a single Shelby tube sample could be taken (a second was tried and failed due to the block being too hard). The hole has no voids and no free liquid.
- A hammer and chisel were used to take the remaining sample.
- The pieces do not crush, crumble, or mold together.
- The material is white and very hard.

SALTCRETE TRIWALL AND METAL SAMPLING

January 20-21, 1992

31. Triwall #3440 (HNUS # SC-31XXX-T) Dated 9/20/87

- The liner was in good condition, with no tears.
- The top of the block was light grey, dry, dusty and was covered with dry flaky particles.
- Penetrometer Readings: 4.5, 4.5, 4.0, 2.5, 4.0.
- The Shelby tube was inserted using a forktruck to a depth of 4 inches and a sledgehammer to a depth of 1½ feet.
- The sides of the Shelby tube hole had no voids, and smooth walls.
- The remaining sample was taken using a hammer and chisel. As the material broke away from the block it became quite sandy.
- The sample had to be taken from the total exposed surface, and only went about 6 inches deep.
- The material was not sticky and some areas were more white in color than light grey. Some larger pieces were collected, but these crumbled with handling.

32. Triwall #2410 (HNUS # SC-325XX-T) Dated 7/10/87

- The liner was in poor condition with many tears due to expansion of the triwall.
- The top was light brown to tan in color, with a dry flaky material on top.
- Penetrometer Readings: 1.0, 0.5, 1.25, 0.75, 0.
- The forktruck was used to force the Shelby tube into the triwall, about 1½ feet. The sides of the Shelby tube hole had no voids and the walls were smooth.
- The sample was collected from the exposed surface to a depth of about 6 inches using a hammer and chisel.
- The material is tan, dry, dusty, and not sticky.

33. Triwall #3018 (HNUS # SC-33XXX-T) Dated 5/28/87

- The liner was in good condition with some flakes of material stuck to it.
- Penetrometer Readings: 4.5, 4.5, 4.5, 4.0, 4.0
- The forktruck was used to force the Shelby tube into the triwall about 6 inches, and a sledgehammer was used to pound the Shelby tube to a total depth of 1½ feet.
- The sides of the Shelby tube hole were smooth and looked slightly glazed, with no voids and no free liquid.
- A hammer and chisel were used to take the remaining sample.
- The material broke off in large chunks which could be crushed by hand into smaller chunks (not dust).
- The material was light grey with some white spots, dry and dusty, and a mixture of chunks, sand, and dust.

34. Triwall #02539 (HNUS # SC-34XXX-T) Dated 12/26/86

- The liner was in good condition, with no tears and no discoloration of the inside.
- No material was adhered to the inside of the liner, while some of the cardboard was adhered to the outside of the liner.
- Penetrometer Readings: 4.5, 2.75, 3.0, 2.0, 3.0.
- The forktruck was used to force the Shelby tube into the triwall to a depth of approximately 1½ feet.
- The sides of the Shelby tube hole were smooth with no voids and no free liquid.
- A chisel was used to take the remaining sample, breaking the material into chunks. These chunks can be broken into two pieces by hand, but cannot be crushed. The bulk sample was taken to a depth of about 6 inches.
- The material was grey in color, and while appearing dry, had more moisture in it than the previous samples, giving it a clay-like texture.

35. Triwall #3037 (HNUS # SC-355XX-T) Dated 5/27/87

- The liner was in good condition, with no tears and no discoloration.
- The bag was not stuck to the liner, and no material flakes were stuck to the liner.
- There was some fading of the cardboard to the outside of the liner.
- Penetrometer Readings: 3.5, 3.0, 3.0, 3.0, 3.0.
- The forktruck was used to push the Shelby tube into the triwall to a depth of approximately 1½ feet.
- The sides of the Shelby tube hole were smooth with no voids and no free liquid, and had a darker grey color than the top of the block.
- The remaining sample was taken using a chisel and spoons to a depth of 6-8 inches.
- The material collected was large chunks with some small particles.
- The material was grey in color, and a darker grey on the worked surfaces.
- The material was dry but has more moisture than the previous sample, giving it a clay-like texture.

36. Triwall #4634 (HNUS # SC-36408-T) Dated 12/11/88

- The liner was in good condition, and while not discolored at the top of the triwall, it had orange discoloration at the sides.
- The top of the block was grey with white swirls.
- The material at the top of the block appears dry and crusty, but was not dusty and is brittle.
- Penetrometer Readings: All > 4.5
- The sledgehammer was used to drive the Shelby tube into the triwall.
- The sides of the Shelby tube hole were smooth with no voids and no free liquid.
- The remaining sample was taken using a hammer and chisel.
- The material was hard, and was chipped off the block creating both fines and 3 inch slabs.
- The material was difficult to break, but was easily chopped up using the chisel (time consuming).
- While the top of the block had a dry crust, the inside had a partially grainy-partially amorphous appearance.

37. Triwall #3817 (HNUS # SC-37408-T) Dated 5/13/88

- The liner had an orange discoloration where in contact with the block.
- The top of the block was grey with a sandy surface appearance, looking like a beach, with the middle smooth in appearance and the edges dry.
- Penetrometer Readings: 3.5, 2.0, 1.0, 1.5, 2.0.
- The sledgehammer was used to drive the Shelby tube into the triwall, and went through the first 4 inches easily and the rest of the way with great difficulty. It was even harder to remove the Shelby tube.
- The sides of the Shelby tube hole were very smooth and dark grey.
- The hammer and chisel were used to take the remaining sample.
- The material pressed together when squeezed, but easily fell apart.
- The material was damp, not dusty, and did not feel really gritty like sand.
- About 8 inches in the triwall a strong ammonia smell was released.
- The duplicate sample was taken from this block.
- The label stated a gross weight of 1675 pounds.

38. Triwall #3886 (HNUS # SC-38408-T) Dated 5/19/88

- The liner was intact, but was orange, brittle, and stiff where in contact with the triwall.
- The top of the block was white and grey and had particulates spread across it.
- The top was very hard and has air-bubble-like voids across the surface.
- Penetrometer Readings: All > 4.5
- It was very difficult to insert the Shelby tube into the triwall, and during removal the entire block lifted off the pallet before the tube released.
- The hammer and chisel were initially ineffective in sampling as the chisel could be pounded into the block but the material would not shatter. The hammer and chisel were used to break/scrape material off the top.
- The material ranged from fines to 3 inch slabs.
- The material from the top of the triwall was dry and dusty while that from the inside was more of an amorphous damp cement.
- No voids and no free liquid were observed.
- When struck together, the larger pieces would "ring" like hard, dense, rocks.

39. Triwall #4381 (HNUS # SC-39408-T) Dated 10/4/88

- The liner was orange and stiff where in contact with the block.
- The material on the top of the block was light brown, and the material underneath it was dark brown.
- Penetrometer Readings: All 3.0
- The Shelby tube went easily all the way to the bottom of the triwall using the sledgehammer.
- The sides of the Shelby tube hole were smooth with no voids and no free liquid. The liner at the bottom of the block is also orange.
- The remaining sample was taken by digging it out of the block with the chisel.
- The material was grey-green in color with some light colored particulates.
- The material from the inside of the block had a stiff clay-like consistency which squeezed easily together and held shape.

40. Triwall #3882 (HNUS #SC-40408-T) Dated 5/18/88

- The liner was orange where in contact with the block.
- The top of the triwall was damp looking but very hard, like a partially dried clay.
- Penetrometer Readings: All > 4.5.
- The Shelby tube drove in with difficulty using the sledgehammer, but only about 12 inches of sample would stay in the tube.
- No voids and no free liquid were apparent in the Shelby tube hole.
- The drill was tried in order to obtain sample from the center of the block but the material only coated the drill bit and looked soft and gooey.
- The material that was sampled using the hammer and chisel was grey, impossible to break, and does not mold together when squeezed.

41. Triwall #4099 (HNUS # SC-41408-M) Dated 1/6/87

- This triwall was in a metal container.
- The side of the triwall was sampled not the top.
- The liner was discolored to a red brown, was very brittle, and broke when cut away from the block. The pieces of liner pulled easily and cleanly away from the block.
- Penetrometer Readings: 4.0, > 4.5, > 4.5, > 4.5, > 4.5.
- It required a great deal of force to insert the Shelby tube into the block.
- The sides of the Shelby tube hole showed no voids and no free liquids.
- The hammer and chisel were used to break up the material and a shovel was used to scoop it out of the block.
- The material broke into 1 to 2 inch pieces and fine particulate.
- The material was light grey and while very hard, it was like fines pressed to a high density, which could be crumbled apart.

42. Triwall #4440 (HNUS # SC-424XX-T) Dated 10/8/88

- The liner was clear and pliable at the top, but became brittle and rust colored near and at the block surface.
- The material did not stick to the liner and some dry flakes fell off the liner when handled.
- Penetrometer Readings: 3.0, 3.0, 2.0, 3.5, 3.5.
- The forktruck was used to push the Shelby tube all the way to the bottom of the block.
- The sides of the Shelby tube hole were smooth with no voids and no free liquid.
- The chisel (no hammer) and shovel were used to take the remaining sample.
- The material scooped easily and broke into 2 to 3 inch pieces.
- The material was a medium grey and slightly damp.

43. Triwall #3287 (HNUS # SC-435XX-T) Dated 6/7/88

- This triwall was in metal container M001115.
- The liner was dark orange and cracked.
- The top of the block was light brown with rust colored particulates.
- Penetrometer Readings: All zero.
- The sledgehammer was used to easily push the Shelby tube into the block.
- Spoons were used to take the remaining sample.
- The material varied between light brown and grey and had a sandy texture. The material was dry in appearance.
- The material could be pressed together, but crumbled easily.
- No voids and no free liquid were observed.
- This block was also used for the duplicate sample.

44. Triwall #3093 (HNUS # SC-445XX-T) Not Dated

- This triwall was in metal container M001115.
- The liner was dark orange and visibly cracked.
- Penetrometer Readings: All zero.
- The Shelby tube was easily pushed into the triwall.
- The remaining sample was taken using the spoons.
- The material was a light grey to white, dry, sandy particulate.
- The material pressed together, but crumbled easily.
- No voids and no free liquid were observed.

SALTCRETE HALFCRATE AND METAL SAMPLING

January 27-30, 1992

45. Halfcrate # PC 804-776-A-5560 (HUNS # SC-455XX-H) Dated 6/29/89

- EG&G carpenters cut a 2'x2' hole in the top of the halfcrate.
- The liner looked okay, the top of the block was grey.
- Penetrometer Readings: All > 4.5.
- The triwall was too hard to push the Shelby tube into it. All sampling was done using a hammer and chisel.
- The material cme off in either slabs or fines.
- There was no free water and the material was very dry and dusty.
- The block appeared to get harder the deeper the sample.
- Sample was taken from as deep as 10 inches (22 inch total thickness).
- The drill was tried for sampling, and the shavings were wet enough to easily mold together. This may have been due to sample compression squeezing the water out. The hammer and chisel were used to the same depth, and the material was dry.
- No voids were apparent.

46. Halfcrate # 748-00032 (HNUS # SC-465XX-H) Dated 12/15/89

- Also written on the label was: Drum # H00110, Waste Stream 09140, Bldg. 374.
- Penetrometer Readings: All > 4.5.
- The Shelby tube could only be driven in about 8 inches. The sides of the hole were very smooth, medium and dark grey in color, with no voids and no free liquid. Some fines were observed in the bottom. The Shelby tube sample was not kept.
- All samples were taken using the hammer and chisel.
- The material came off the triwall in thick slabs and fines.
- The material was light grey and dry inside the block, and hard to a depth of at least 6 to 8 inches.
- The larger pieces could not be broken by hand, and did not ring when struck together.
- No voids and no free liquid were apparent.

47. Halfcrate # H00264 (HNUS # SC-475XX-H) Dated 4/8/90

- Penetrometer Readings: All > 4.5.
- The block was too hard to sample using the Shelby tube. All samples were taken using the hammer and chisel.
- The material tended to dust or slab when chiseled.
- The material was a light brown to grey in color and the sample was primarily fines.
- The larger pieces could not be broken by hand, and sound solid, but do not ring when struck together.
- The halfcrate was sampled to a depth of 6 inches and no voids and no free liquid were observed.

48. Halfcrate # H03453 (HNUS # SC-485XX-H) Dated 4/5/91

- The liner had no discoloration.
- The top of the block was a white crust with dark grey material underneath.
- The dark grey material looked like pumice with holes up to 1/8 inch diameter.
- Penetrometer Readings: All > 4.5.
- The Shelby tube could not be used as the top was too hard.
- The drill was tried to a depth of about 10 inches, but the shaving produced were very wet and almost slowed the drill to a standstill.
- The hammer and chisel were used to take all of the sample.
- When broken, the exposed surface looked dark grey which changed to a lighter grey within a few minutes.
- The block had primarily smooth faces inside with some small voids, like the top. No free liquid was observed.
- The sample was a 50/50 mixture of fines and coarse material.
- The large pieces do not "ring" when struck together.

49. Halfcrate # H03202 (HNUS # SC-495XX-H) Not Dated

- The liner was clear and in good condition. The material was not stuck to it.
- Penetrometer Readings: All > 4.5.
- All samples were taken using a hammer and chisel.
- The material was light grey in color and came off the block in 1 to 5 inch chips.
- The material was dry and no voids and no free liquid were observed.

50. Halfcrate # H00198 (HNUS # SC-505XX-H) Not Dated

- The liner was clear and in good condition.
- Penetrometer Readings: All > 4.5.
- A hammer and chisel were used to take all of the samples.
- The material broke into 1 to 5 inch chips which scattered when struck with the chisel.
- The material was grey and varied from dry hard chips to a clay-like material which could be crumbled.
- No voids and no free liquid were observed.

51. Halfcrate # 748-00466 (HNUS # SC-515XX-H) Dated 9/30/91

- Penetrometer Readings: All > 4.5.
- All samples were taken using a hammer and chisel.
- The block was very hard requiring a lot of force to chip off the samples.
- The material shattered fairly cleanly creating very little dust.
- The material was grey in color, dry, very hard and broke into large chips.
- The material could not be broken by hand and was not sticky nor flowable.

52. Halfcrate #776-A-6189 (HNUS # SC-525XX-H) Dated 6/28/89

- The liner was in good condition with no cracks.
- Penetrometer Readings: All > 4.5.
- All sampling was performed using a hammer and chisel, and alot of force was used.
- The material was grey and dry, and while very hard to break, some of the pieces were crumbly.
- The material broke into large chunks and a fine dust.
- No voids and no free liquid were observed.

53. Halfcrate # HO-776-A-5441 (HNUS # SC-535XX-H) Dated 6/1/89

- The liner had a reddish discoloration, but was intact.
- No material was stuck to the liner, but it was covered with fine particles.
- Penetrometer Readings: All > 4.5.
- All samples were taken using a hammer and chisel, and required moderate force.
- The material tended to shatter off of the block in big pieces.
- The material was grey, dry, very hard and broke into large pieces and fines.
- No voids and no free liquid were observed.

54. Halfcrate # H00277 (HNUS # SC-545XX-H) Dated 4/9/90

- The liner was clear, intact, and clean except for particulate dust.
- The block was grey, hard and dry.
- Penetrometer Readings: All > 4.5.
- Samples were taken using a Shelby tube, and hammer and chisel. It did not require much force to sample the block.
- The material was grey and dry, and crumbled easily to produce small fines. No large pieces were produced in sampling.

55. Halfcrate # H03509 (HNUS # SC-555XX-H) Dated 5/9/91

- The liner looked clear and intact, with no material stuck to it.
- The top of the block was covered with a 1/4" thick white crust. Underneath the crust the material was grey.
- Penetrometer Readings: All > 4.5.
- The samples were taken using the hammer and chisel, and drill.
- It required a great deal of force to chip pieces off of the block, "like breaking up a sidewalk with a toothpick".
- The material breaks into pieces about 3 inches across and 1 inch thick. The chisel would not score the material easily.
- The chips were grey, dry, and porous, like pumice.
- The material did not press together when squeezed, but the larger pieces could be broken by hand.
- No free liquid was observed.

56. Halfcrate # H03211 (HNUS # SC-565XX-H) Dated 12/18/90

- The liner looked new.
- The top of the block was covered with a white crust approximately 1/16 inch thick. Across the top of the white crust appeared to be salt crystals. Underneath the crust the material was grey.
- Penetrometer Readings: All > 4.5.
- All sampling was performed using a hammer and chisel and the block was very hard.
- The material broke off the block in dry, thin, slate-like chips.
- The block was very hard to sample, and no voids or free liquid was observed.

57. Triwall # 2739 (HNUS # SC-57408-M) Dated 3/22/87

- This triwall was in metal container M00661.
- The liner had a slight orange discoloration.
- The top of the block was white and covered with dusty white granules.
- Penetrometer Readings: All 0.
- The Shelby tube was easily pushed into the block using the sledgehammer.
- The remaining sample was taken using the chisel and spoons.
- The material was dry, soft, breaks easily to a sand texture, and does not press together when squeezed.
- No free liquid was observed.
- Some artificial voids were created by the plastic liner folding into the block.

58. Triwall #2804 (HNUS # SC-58408-M) Dated 4/7/87

- This triwall was in metal container M00661.
- The liner was discolored orange and was cracking.
- The top of the block was yellow with a layer of off-white granules under the surface. Underneath the granules the block was grey.
- Penetrometer Readings: 2.5, 2.0, > 4.5, > 4.5, 4.0.
- The Shelby tube was inserted into the block using the sledgehammer.
- The remaining samples were taken using the chisel.
- The material could be pressed together by hand, but crumbled easily.
- The material was dry in appearance, medium gravel size, and was slightly adhesive.
- No voids and no free liquid were observed.

59. Triwall #748-03257 (HNUS # SC-595XX-M) Dated 7/21/89

- This triwall was in metal container M00424.
- The liner was orange and torn.
- The top of the block was grey, dry and looks like sand.
- Penetrometer Readings; Conflicting, probably zero.
- The Shelby tube was easily pushed into the block by hand.
- A shovel was used to take the remaining samples.
- The inside of the block was a greyish white, and no voids and no free liquid were observed.
- The material was a very fine, soft grey-white sand.

60. Triwall # 748-3226 (HNUS # SC-605XX-M) Dated 7/12/89

- This triwall was in metal container M00424.
- The liner was orange and torn.
- Penetrometer Readings: 0.25, 0.25, 1.0, 1.0, 1.5.
- The Shelby tube inserted easily by hand.
- A shovel was used to take the remaining sample.
- The material was greyish white with some brown areas, with a moist, flour-like texture.
- Though a fine particulate, the material was slightly adhesive.
- No voids and no free liquid were observed.

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Procedure No.: Page:

212B, Rev 0, Draft D

49 of 57

Category 3

DRAFI

Effective Date: Proposed:

November 10, 1991

Organization:

Waste Operations

EG&G ROCKY FLATS, INC.	
SAMPLE DATA SHEET 1	
PONDCRETE MATERIAL	
SAMPLE IDENTIFICATION No. : P-748-04104 50	
SOURCE: TENT No. : 8 Stack 9 DATE No. : PAD No. : 904 MOO 818 TIME No. :	
BOX LABEL INFORMATION :	
SAMPLE METHOD: SMAPLE DESCRIPTION	· · · · · · · · · · · · · · · · · · ·
DRILL D SOLID HAMMER & CHISEL D MOISTURBED SEMI SOLID (PLAST SHEBLY TUBE SAMPIK. SLUDGE SHOVEL SIOTHER:	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READI white who orange steips DRY-DUST Kentop CRUMBS - Clumps Crum	
1 shelby tube w/ shoull pent-contex 210, 3.75, 5.0, 2.75, 5.0 Material is DRY No Free liquid	
	(date)
SAMPLER'S NAME (print) (signature)	(Gate)
Douglas Pretzer Miller	1-7-92
RECORDER'S NAME (print) (signature)	(date)
STEVE DAVIS Steven & Davy	1-7-92

) · 50-02408· T

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D

49 of 57 November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE, MATERIAL				
SAMPLE IDENTIFICATION No. : P-181 03873				
SOURCE: TENT No. : 5 5 PAD No. : 164	DATE NO.			
BOX LABEL INFORMATION :				
SAMPLE METHOD:	SMAPLE DESCRIPTIO	N :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PL. SLUDGE OTHER :	ASTIC)		
REMARKS: (e.g. COLOR, TEXTURE, No Light Gray, Mass fials	OF GRABS, MONITOR RE.	ADINGS, etc.)		
Penetrometer tests (5) 4,5.4 Do voids exist? ill: To there from liquid 110 Material wet or dry Ding	5,45,2.5,75			
SAMPLER'S NAME (print) M. P. M. M.	(signature)	(date) <u>i-13-72</u>		
RECORDER'S NAME (print)	(signature)	(date) /-/2-412		
1/4 1/04/4	ecallic			

SC-03408-7 and X-03408-7-D

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Procedure No.:

212B, Rev 0, Draft D

Page:

49 of 57


Category 3

DRAFI

Effective Date: Proposed: Organization:

November 10, 1991 Waste Operations

EG&G ROCKY	FLATS, INC.
SAMPLE DAT	TA SHEET 1
PONDCRETE	MATERIÁL
SAMPLE IDENTIFICATION No. : P-	03912 Saltcrete
SOURCE: TENT No. : 8 9 PAD No. : 904	TACLE NO. : 5-22.88 TIME NO. :
BOX LABEL INFORMATION :	
SAMPLE METHOD:	SMAPLE DESCRIPTION :
DRILL E HAMMER & CHISEL X SHEBLY TUBE X CONDISTA SHOVEL X	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:
Light gray folk white some particulates roc	le salt sized) + smaller material combe pressed together
Pentrameior text 50 2.5 2	2.5 4.0 2.0 / perticulates
SAMPLER'S NAME (print)	(signature) (date)
R. WILLIAMS Sec	altable 1-1397
RECORDER'S NAME (print)	(signature) (date)
STEVEN DAVIS	twen I Daw 1-1392



EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Procedure No.:

212B, Rev 0, Draft D

. ---

Page:


49 of 57

Category 3 DRAFI

Effective Date: Proposed: Organization:

November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC.		
SAMPLE DATA PONDCRETE I		
SAMPLE IDENTIFICATION No. : P-03	2.11	
SAMPLE IDENTIFICATION NO. : 1-03	JAVIA I	
SOURCE: TENT No. : 7 PAD No. : 704	DATE No. : 5-17-88 TIME No. :	
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
properties. But material stil	like (medium sand) gether and has some clay-like crembles easy 1.5 most off scale	
SAMPLER'S NAME (print)	(signature) (date)	
R. Withers offer	1-13-92	
RECORDER'S NAME (print)	(signature) (aate)	
STEUE DAVIS	tern & Davi 1.13-92	



EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D

49 of 57 November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC.		
SAMPLE DATA		
PONDCRETE M		
SAMPLE IDENTIFICATION No. : P-379	10 stack & Salterete	
SOURCE: TENT No. : 16 3100 PAD No. : 904	TOVE NO. : SECO	
BOX LABEL INFORMATION : 3890		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
There sending 2 partial	of graes. Monitor READINGS, etc.) not, had to use Forks ser shelly enerwhite dubt shelly tube e way around (5.0)	
SAMELER'S NAME (print) KICHILLAMS Sank	(signature) (date)	
RECORDER'S NAME (print) MICHELE HERSHEY	(signature) (date)	

EG&G ROCKY FLATS PLANT

WR&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Crgandaion:


2128, Rev 0, Draft D

49 of 57

November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL				
SAMPLE IDENTIFICATION No. :	= Stack = Saltante			
SOURCE: TENT No. : 10 PAD No. : 909				
BOX LABEL INFORMATION : 2	3956 6-23-58			
SAMPLE METHOD:	SMAPLE DESCRIPTION :			
DRILL IN THE SHEEL IN THE SHOVEL IN THE INTERPRETATION INTERPRETATION IN THE INTERPRETATION INTERPRETATION IN THE INTERPRETATION INTERPRETATION INTERPRETATION INTERPRETATION INTERPRETATION INTERPRETATION INTERPRETATION I	SCLID SEMI SOLID (PLASTIC) SLUDGE OTHER:			
and dakes who and the shelly and it was yo	JRE, NO. OF GRABS, MONITOR READINGS, etc.) white, texture hand n hit is hammer and Chisil tule sample was taken intially full SED ALL THE WAY Alound.			
SAMPLER'S NAME (print)	(date)			
Fick WilliAms	Juk Willia 1-13-92			
RECORDER'S NAME (print)	(signature) (date)			
M.L. HERSHEY	Michello Mershey 1-13-92			



EG&G ROCKY FLATS PLANT WA&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

2129, Rev 0, Draft D 49 of 57 November 10, 1991 Waste Operations

ATTACHMENT 1

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. : P-7	745-174226 Saltons	te	
SOURCE: TENT No. : $\frac{8}{104}$	tack F DATE No. : 3-1 TIME No. : _	<u>0-88</u>	
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :	·	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	X	
light Hown, dry parting with fine that leakens & wids pro locks, Very no when broke up.	rut. Fine dry Jourtes.		
Doughs exist 170 Ever weren 7 10			
SAMPLER'S NAME (print)	(signature)	(date)	
RC. Angaiano	Al Anguara 1	-1492	
RECORDER'S NAME (print)	(signature)	(date)	
Ka DiSala	Marisalle 1	14-92	

8

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57

November 10, 1991 Waste Operations

EG&G ROCKY	FLATS INC.
SAMPLE DAT	A CHEFT 1
SAMPLE DAT	MATERIAL
PONDCRETE	
SAMPLE IDENTIFICATION No. : P-	108-13724 - Satisfiete
SOURCE: TENT No. : 8 Sto	DATE No. : <u>17-,28-</u> 87 TIME No. :
BOX LABEL INFORMATION :	
SAMPLE METHOD:	SMAPLE DESCRIPTION :
SAMPLE METHOD.	SCL!D
ORILL S	SEMI SOLID (PLASTIC)
HAMMER & CHISEL SHEBLY TUBE	SLUDGE
SHOVEL	OTHER:
REMARKS : (e.g. COLOR, TEXTURE.)	10. OF GRABS, MONITOR READINGS, etc.)
1 Client and and a will a simple	THE THE CHARLES THE PARTY OF TH
	intaritly. Il lazzury sticks together
slightly then chumines. Fin	Poure
· · · ·	
Pentrometer text 1.5	0,1.0,15,1.5
Moternal wet by dy ?	4
Do voids exist	
Ever worey ?	/ /
SAMPLER'S NAME (print)	(signature) (date)
	1. 11. Bounds 1-14-90
Bradley Bounds 1	Sadlinitaurdo 1-14-90
1-11-11-11-11-11-11-11-11-11-11-11-11-1	
RECORDER'S NAME (print)	(signature) (date)
RECORDER 3 NAME (PONT)	(2 2
Ka. Disalla -	+abisaile 1-14-92

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:


Organization:

212B, Rev 0, Draft D

49 of 57 November 10, 1991

Waste Operations

SAMPLE D	KY FLATS, INC. DATA SHEET 1 TE MATERIAL		
SAMPLE IDENTIFICATION No. : E	<u>- 748</u> - ,7	Satterete	
SOURCE: TENT No. : 3 PAD No. : 904	Stack 3 DATE I		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIP	TION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID SLUDGE OTHER :	(PLASTIC)	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Matquiat is liant Dian, with white many musica Emps and particulated on top. Lair than amount Smell. Samples any minimized. Do what stick together			
Pentrometer text > 4.5 4 Material wet or dir Dry Do upins exist 10 Ever weren 7 110	15, 4.5, 4.5, 4.5		
SAMPLER'S NAME (print)	(şignoture)	(date)	
Mark DAGOSTINO	M DK Joshir	1-14-92	
RECORDER'S NAME (print)	(signature)	(date)	
K.a. Disalle	Hilanule	1-14-92	



Procedure No.: Page:

212B, Rev 0, Draft D 49 of 57

Category 3

DRAFI


Effective Date: Proposed:

November 10, 1991

Organization:

Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL	
SAMPLE IDENTIFICATION No. : P-04031 Saltacete	
SOURCE: TENT No. : zert & DATE No. TIME No.	: <u>7-7</u> 8 8
BOX LABEL INFORMATION :	
SAMPLE METHOD: SMAPLE DESCRIPTION	N :
DRILL SOLID HAMMER & CHISEL & SEMI SOLID (PLA SHEBLY TUBE & SLUDGE SHOVEL D OTHER:	кsпс) <u>В</u>
REMARKS: (e.g. COLOR, JEXTURE, No. OF GRABS, MONITOR REA Light arch in white streets Matinal Drobe into mea to sperse sex Cruble-Material was pressed in to ball rack type, material could not be pressed a	. 2
Pentrometer test 4.0 50 50 4.5 4.5 Material With on dry DRY Pownish exist? No Ever were, ? None	
SAMPLER'S NAME (print) (signature)	(date)
R. WILLIAMS Schaller	1-14.92
	(date)
RECORDER'S NAME (print) (signature) STEVEN & Daws Steven 1) Davis	1-14-9Z



Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

2128, Rev 0, Draft D 49 of 57 November 10, 1991

November 10, 1991 Waste Operations

EG&G ROCKY F		
SAMPLE DATA	SHEET 1	
PONDCRETE A	MATERIAL	
SAMPLE IDENTIFICATION No. : P-04	LOS9 SALTCRETE	
SOURCE: TENT No. : 3 46 PAD No. : 904	DATE No. : 2	7-4-88
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC SLUDGE OTHER :	. G C) O ————————————————————————————————————
REMARKS: (e.g. COLOR, TEXTURE, No. Light gray in / 2/1 str Material Drieke into Elump Resil, broken, Material Dree texture Pentromely text All readings Moterial wet or dig Dry Sures Pounds exist? No Ever warey 7 No	s - clumps themselve air down into coar	
SAMPLER'S NAME (print)	→ (signature)	(date)
R WILLIAMS Kin	Met Mille	1-14-92
RECORDER'S NAME (print)	(signature)	(date)
	≠ // ÿ /	1 - 14 . 4 /

EG&G ROCKY FLATS PLANT

Procedure No.:

212B, Rev 0, Draft D

WR&S Operating Procedures

Page:

49 of 57

Category 3

DRAFI

Effective Date: Proposed:

November 10, 1991

Organzaion:

Waste Operations

EG&G_ROCKY_FLATS, INC.	
SAMPLE DATA SHEET 1	
PONDCRETE MATERIAL	•
SAMPLE IDENTIFICATION No. : P- 04 \$36 Salterche	
SOURCE: TENT No. : 7 Stack DATE No. PAD No. : 904 TME No. :	<u> 10-10</u> -88
BOX LABEL INFORMATION :	
SAMPLE METHOD: SMAPLE DESCRIPTION	:
DRILL I SOLID HAMMER & CHISEL A SEMI SOLID (PLAS SHEBLY TUBE A Undisturbes SLUDGE SHOVEL I OTHER:	ж sпc) <u>п</u> п
REMARKS : (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READ	
white form with very thin paper like +	Claked medica
Sand texting - material acts like do.	
can be pressed, smeared and formed be	it can also
Pertromein text All 5	
Material wet or die Dry	
Do unids exist No	
Ever were, ? Vane	
SAMPLER'S NAME (print) (signature)	(date)
RECORDER'S NAME (print) (signature)	(date)
Steven DAys Steven Dow	1-14.92

Procedure No.:

212B, Rev 0, Draft D

Page:

49 of 57

Effective Date: Proposed:

November 10, 1991 Waste Operations

Category 3

DRAFI

Organization:

ATTACHMENT 1 SAMPLE DATA SHEET 1

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL

PONDORETE MATERIAL			
SAMPLE IDENTIFICATION No. : P-03	JCTICA CA		
SOURCE: TENT No. : 8 SPA	DATE No. : <u>5-13-88</u> TME No. :		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID X SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) white with gray sploteles - slightly Dump - can press small perticles together material clumped - broken down to med. Sand/gravel			
Pentrometer text 4.5 Center 4.5 4.5 4.5 4.5 4.5 4.5 Material wet or dir ? Dry - Do upids exist? No Ever warer? None			
SAMPLER'S NAME (print) Doug Portzer	(date) (date) (1/14-9Z		
RECORDER'S NAME (print) STEUR DAVIS	(signature) (date) Lever Day 1-14-92		

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

2128, Rev 0, Draft D 49 of 57 November 10, 1991

Waste Operations

	JKY FLAIS, HYU. Data queet 1
1	DATA SHEET 1 ETE MATERIAL
SAMPLE IDENTIFICATION No. :	=-03937 Salturete
SOURCE: TENT No. : 8 PAD No. : 90	Stack O DATE No. : <u>6-20-88</u>
BOX LABEL INFORMATION :	
SAMPLE METHOD:	SMAPLE DESCRIPTION :
ORILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SCLID . & . SEMI SOLID (PLASTIC) D SLUDGE D OTHER:
50 me porticulates an	RE, No. OF GRABS, MONITOR READINGS, etc.) ** /igh+ gray top. ** top. ** clay: ** Clay: ** Clay: ** Around
SAMPLER'S NAME (print)	(signature) (date)
Douglas C. Pretzer	Cayla (1-14-92
RECORDER'S NAME (print)	(signature) (date)
STEVE DAVIS	Steven Jan 1-11-97

Procedure No.:

212B, Rev 0, Draft D 49 01 57

Page:


Category 3

DRAFI

Effective Date: Proposed: Organization:

November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P- 0	4174 SALTCRETE	
SOURCE: TENT No. : \$ \$1.00 PAD No. : \$24	DATE No. : Aug 17-88 TIME No. :	
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL D HAMMER & CHISEL D SHEBLY TUBE SHOVEL DCOOP	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
REMARKS: (e.g. COLOR, TEXTURE, No. Brown / rest color Medium to fine mat/ could be pre crumbled very easily Pentrometer text — O — Material wet or der? Dry Po upins exist? No Ever weren? No	Desty	
SAMPLER'S NAME (print)	signature (date)	
RECORDER'S NAME (print) STEVE DAVIS	(signature) (date)	



Category 3

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organdaph:

212B, Rev 0, Draft D 49 of 57

November 10, 1991 Waste Operations

EG&G ROCKY I SAMPLE DATA PONDCRETE	A SHEET 1
SAMPLE IDENTIFICATION No. : P-C	
SOURCE: TENT No. : 8 901 51 PAD No. : 304	DATE No. : 8-9-88 TIME No. :
BOX LABEL INFORMATION :	
SAMPLE METHOD:	SMAPLE DESCRIPTION :
DRILL □ HAMMER & CHISEL □ SHEBLY TUBE SHOVEL SCOOP □	SOLID . Ø SEMI SOLID (PLASTIC) — SLUDGE — OTHER :
material can be pressed tough to insert Shelly Pentromer toxt 4,5 center	te (yellowish) to insert Shelly tube tube
Material wet or dry Dry - Do unids exist? Mo Ever weren? Done	Dusty
SAMPLER'S NAME (print) OJ Goetz	(signature) (date) 1-15-92
RECORDER'S NAME (print)	(signature) (date) Leven J Zam 1-15.52

(17)

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:


Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57

November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC.		
SAMPLE DATA SHEET 1		
PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-02828 Saltcrute		
SOURCE: TENT No. : P Stack 0? DATE No. : 41-10-87 PAD No. : 207 TIME No. :		
BOX LABEL INFORMATION :		
SAMPLE METHOD: SMAPLE DESCRIPTION :		
DRILL SOLID SOLID (PLASTIC) SHEBLY TUBE SHOVEL OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) white gray 5and Very 50ft 5/1+- material does press together Disty 5plits in liner		
Pentrometer text O 50A 5and (Fine) Material wet or dry Dry Do upids exist? No Ever werer? Nove		
SAMPLER'S NAME (print) (date)		
C. T. GOETE Calcond 1-15-92		
RECORDER'S NAME (print) (signature) (date)		
STEUR DAVE Steven Paris 11592		



Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

2128, Rev 0, Draft D 49 of 57

November 10, 1991 Waste Operations

EG&G ROCKY F	LATS, INC.		
SAMPLE DATA	SHEET 1		
PONDCRETE A	MATERIAL		
SAMPLE IDENTIFICATION No. : P- 02	2225 saltome		
SOURCE: TENT No. :PAD No. :	DATE No. : 10-13-86 TIME No. :		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Med - and texture - matical are a priced at a titled when the first Most Direct works are mid and coumbs about golf bell sized Pentrometry text 3.5 1.0 36 1.5 1.0 Material wet or dyn Dry Do upins exist? Na Ever warey 7 None			
SAMPLER'S NAME (print) XILLER'S NAME (print)	(signature) (date) (date) (1-15-92		
RECORDER'S NAME (print) STEVE DAVIS	(signature) (date) Thirtie 1-15-92		

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

2128, Rev 0, Draft D 49 of 57 November 10, 1991 Waste Operations

EG&G ROCKY F SAMPLE DATA	SHEET 1	
PONDCRETE A	MATERIAL	
SAMPLE IDENTIFICATION No. : P-0	3011	
SOURCE: TENT No. : PAD No. :	DATE No. : <u>5-Zz-87</u> TME No. :	
BOX LABEL INFORMATION :		-
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	•
REMARKS: (e.g. COLOR, TEXTURE, No.		
Pentromein text 1.0 around Material wet or dy? Dr. Do upins exist? No Ever werey? None	Jang Class	- -
SAMPLER'S NAME (print)	(date)	
Remare Celilliams La	Wille 1.15-92	•
RECORDER'S NAME (print)	(signature) (date)	
STEVE TAVIS SI	ever 2 / Jana 1-15-62	



SC-205 XX- T

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Procedure No.:

212B, Rev 0, Draft D

49 of 57

Category 3

DRAFI

Page: Effective Date: Proposed:

November 10, 1991 Waste Operations

Organization:

1211.

	=1 . === 12.0		
EG&G ROCKY FLATS, INC.			
	SAMPLE DATA SHEET 1		
PONDCRETE	MATERIAL		
SAMPLE IDENTIFICATION No. : P-	<u>03</u> 282		
SOURCE: TENT No. : PAD No. :		7:55	
BOX LABEL INFORMATION : 748-	-02585 UT)4.5 H-02585	25 CBS	
SAMPLE METHOD:	SMAPLE DESCRIPTION	i :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLA SLUDGE OTHER :	TH - SMILMOST	
REMARKS : (e.g. COLOR, TEXTURE, N			
DREY, CLAYLIKE, RASTIC, PLYA		GUS. MOIST	
SURBY HOLE SMOSTAL, DREY, HOMO	CENTONS, HOCOS SWAPE,		
Pentromeico text - 2.0 2.0,3 Moterial wet ou diz Dry CRUI	0.0,1,5,1,75		
Pounds exist 2 NO VOIDS	VIDE, NET		
I've werey ? NO FREE (I OUT	25		
SAMPLER'S NAME (print)	(signature)	(dat e)	
M Dagastino			
RECORDER'S NAME (print)	(signature)	(date)	
VAAL	ADJEU) A PUYEAR	12 1-16-92	

(1) SC-215XX. T

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Procedure No.:

2128, Rev 0, Draft D

. ---

Page:

49 of 57 November 10, 1991

Effective Date: Proposed:
Organization:

Waste Operations

Category 3

DRAFI

			
EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. :	P-02237		
SOURCE: TENT No. :	 /	. : <u>/2-23</u> -86 :	
BOX LABEL INFORMATION :	148-02237		
SAMPLE METHOD:	SMAPLE DESCRIPTION	: NC	
POLKLIFT DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SCLID SEMI SOLID (PI SLUDGE OTHER :	LASTIC) X SEME	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) ALEYTSH, DRY CRUMBLY, TEXTURED, FLAKY, DRADDY - PROPERTY AMMONTA ODORS.			
Pentrometer text 25, 253.0, 3.0, 4.0			
Do upids exist? NO UOTOS			
Ever werey ? NOTHE	(signature)	(date)	
SAMPLER'S NAME (print)	(signotally)	. \(a \)	
m D7 3057,000	M DL 367M	1-10-14	
RECORDER'S NAME (print)	(signature)	(date)	
Vad APyr	CATRIY PUYEAR	1-16-92	

Procedure No.:

212B, Rev 0, Draft D

49 of 57

Category 3

DRAFI

Page: Effective Date: Proposed: Organization:

November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1			
PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. :	<u>2- 3</u> /37		
SOURCE: TENT No. :	DATE NO		
BOX LABEL INFORMATION :	804-3137,		
SAMPLE METHOD:	SMAPLE DESCRIPTI	ON:	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL (SPOONS)	SOLID SEMI SOLID (F SLUDGE OTHER :OL	PLASTIC) [] [] [] [] [] [] [] [] [] [] [] [] [] [
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRAES, MONITOR READINGS, etc.) OFFWHITE ANTIQUEWHITE, FINE PALTICULATES, FLOUR (BAKDUR TEXTURE SOFT, FLY AWAY DLY PARTICULATES ALLTRE WAY THRU, WHEN PULLED OUT SLIGHBY TUBE THE HOLE COLAPSED, (ULDNT HOLD WALL SLATE. ALMOST LOOKS LIKE DLY UNUSED CHMENT-BUT DIFF, COLOR Pentrometer text 0,0,0,0.			
Material wet ou dry DRY Do unids exist? NO Ever werey ? NO			
SAMPLER'S NAME (print)	(signature)	(date)	
M DAgosli	M DAgostiso	1-15-9)	
RECORDER'S NAME (print)	(signature)	(date)	
KATUCEN A PUYEAR	Kid & Pyer	1-16-92	

DRAFI Category 3

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57 November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC.				
	DATA SHEET 1			
	RETE MATERIAL			
SAMPLE IDENTIFICATION No. :	<u>P- 03</u> 456			
SOURCE: TENT No. : <u>8</u> PAD No. : <u>704</u>		<u>9-72-87</u>		
BOX LABEL INFORMATION :	03456			
SAMPLE METHOD: SLEBGE HAMMEL &	SMAPLE DESCRIPTIO	DN :		
DRILL HAMMER & CHISEL	SOLID SEMI SOLID (PL	. □ . ASTIC) □		
SHEBLY TUBE	SLUDGE OTHER :			
FOLKTIFT		101105 -1-1		
REMARKS : (e.g. COLOR, TEXTU	KE, NO. OF GRABS, MUNHOR RE	ADINGS, etc.)		
Pentrometer text 1.5, 1.5, 2.0, 1.75				
Do upids exist? NO				
Iver waren? NO				
SAMPLER'S NAME (print)	(signature)	(date)		
Brad Bounds	Bradly Burnso	1/16/92		
		/		
RECORDER'S NAME (print)	(signature)	(date)		
KADIEN PUYCHR	Col A Payor	1-16-82		

Procedure No.:

2128, Rev 0, Draft D

49 of 57

November 10, 1991 Waste Operations

Category 3

DRAFI

Page: Effective Date: Proposed:

Organization:

SAMPLE D	(Y FLATS, INC.)ATA SHEET 1 TE MATERIAL	
SAMPLE IDENTIFICATION No. : E		
	STACK C DATE NO	7 7 98
SOURCE: TENT No. : 8 PAD No. : 904	TIME NO	
BOX LABEL INFORMATION : 7	48-04084	1741 LBS
SAMPLE METHOD:	SMAPLE DESCRIPTI	ON:
DRILL HAMMER & CHISEL SHEBLY TUBE	SOLID SEMI SOLID (F SLUDGE OTHER:	PLASTIC) D
REMARKS: (e.g. COLOR, TEXTURS COLOR, TEXTURS COLOR, TEXTURS COLOR, TEXTURS AND HOMOLETICAL Pentromeico text S.O. S.O. Material wet or do 7 Do upids exist? Fore warey 7 NO	(PALE SMAU BURIUS - WAR POULDOUS, PUMIC LIKE, C BLOAKS TOTO 3-4, <2-3	HON RULOO)
SAMPLER'S NAME (print)	(signature)	(date)
Brad Bounds	Bradley Barneds	1/16/92
RECORDER'S NAME (print)	(signature)	(date) 1-16-92

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57 November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC.			
SAMPLE DATA SHEET 1			
PONDCRETE A			
SAMPLE IDENTIFICATION No. : P-02			
SOURCE: TENT No. : 2 5+ PAD No. : 304	DATE No. : 1-2-87 TIME No. :		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL G HAMMER & CHISEL Ø SHEBLY TUBE Ø SHOVEL G	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. 5andy textino tar	OF GRABS, MONITOR READINGS, etc.)		
Penetroneter tests (5) Z.5 all Do voids exist? No Is they from liquid No Material wet or day DRY	sand		
SAMPLER'S NAME (print)	(signature) (date)		
Lieuxo Villisms Lio	Mille 11692		
RECORDER'S NAME (print)	(signature) (date)		

EG&G ROCKY FLATS PLANT

Procedure No.:

212B, Rev 0, Draft D

WR&S Operating Procedures

Page:

49 01 57

Category 3

DRAFI


Effective Date: Proposed:

November 10, 1991

Organization:

Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. : P- 0	365		
SOURCE: TENT No. : 7 54 PAD No. : 704	TIME No. : 10-29-87		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) white particulates white particulates white particulates white particulates popped air bubbles on top of block Centropheter tests (5) 4,0 centrol 4,5,4,5,5,0 45 Do voids exist? No			
To there free liquid No Material wet or dry Dry -	DAME		
SAMPLER'S NAME (print)	(signature) (date)		
Richard WILLIAMS SEL	10/1/2 1-16-92		
RECORDER'S NAME (print)	(signature) (date)		
STEVE DAVID	Engs Tavi 1-1692		



Category 3 DRAFI

Procedure No.:

Page:


Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57

November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC.			
SAMPLE DATA SHEET 1			
PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. : P- 0.	3125		
SOURCE: TENT No. : 51 PAD No. :50	DATE No. : 7-10-87		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
ORILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID BL SEMI SOLID (PLASTIC) D SLUDGE D OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No.	Sand next ton		
Penetroneter tests (5) - ALL Z Do voids exist? No Is they fra liquid More Material wet or day Don	-		
SAMPLER'S NAME (print)	(signature) (date)		
Richard Williams Kan	Elleste 1-16-92		
RECORDER'S NAME (print)	(signature) (date)		
STEVE DAVIS 1	teven Par 1-16-97		



⊶

Category 3 DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D

49 of 57 November 10, 1991

Waste Operations

SAMPLE DATA SHEET 1			
PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. :	P- 11 known Taltarete		
SOURCE: TENT No. : PAD No. :	5+nct - DATE No. : 5-25-89		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID ME SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) white sand rem soft mush a clay interior DRY DARTICULATION OF block			
Renetroneter tests (5) -0- Do voids exist? No Ts there free liquid NO			
Material wet or dry	wet inside dry top		
SAMPLER'S NAME (print)	(signature) (date)		
Bichard Williams	Killleller 1-16-93		
RECORDER'S NAME (print)	(signature) (date)		
STEVE DAYS	Steven & Davi 1-16-92		



SE-29408-T

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Procedure No.:

2128, Rev 0, Draft D

vinas operating Ficedure

Page:

49 of 57

Category 3

DRAFI

Effective Date: Proposed:
Organization:

November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1			
PONDCRETE	MATERIAL		
SAMPLE IDENTIFICATION No. : P-0			
SOURCE: TENT No. : F S	DATE No. : 6,5-88		
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. White purhales Texture grand Stan pressed			
Penetrometer tests (+) 4, 5 center Do voids exist? No Ts there free liquid No Material wet or day it.	7.5 27 1/6 3.5 		
SAMPLER'S NAME (print)	(signature) (date)		
Douglas Protosa No	1-16-2-		
RECORDER'S NAME (print)	(signature) (date)		
STEVE PAGE St	1 - 16-55 - 16		

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:


Organization:

212B, Rev 0, Draft D 49 of 57

November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-		
SOURCE: TENT No. : F 51 PAD No. : 201	DATE No. : 4587 TIME No. :	
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Pener. John John Lands Like Demen. John John Lands Like		
= types needed for 12 smaple		
Penetroneter tests (F) 5.6 Cerric 5.0 - 5.0.5.0-11. Do voids exist? (1) To there free liquid 1/0		
To there free liquid 100 Material wet or dry 16!		
SAMPLER'S NAME (print)	(signature) (date)	
Donales C. Protier De	1-16-65	
RECORDER'S NAME (print)	(date)	
STEVE PAVIS	Tenyor 1-16-9E	



Procedure No.:

212B, Rev 0, Draft D

Page:

49 01 57

Effective Date: Proposed: Organization:

November 10, 1991 Waste Operations

Category 3

DRAFI

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. : P-	748-03440		
SOURCE: TENT No. :	DATE No. TIME No. :		
BOX LABEL INFORMATION : 748-	03440 Accounciate 4-2	4-87	
SAMPLE METHOD:	SMAPLE DESCRIPTION	٧ :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLA SLUDGE OTHER :	STIC) (2008)	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Cight gray, soled, when no moissible, use Hammen + chisel to collect remaining samples marinal was savely in some area often Using this methol, some churks work collected but animoised by fouch. Centroheter tests (5) 4.5, 4.5, 4.0, 2.5, 4.0 Do voids exist? NO Ts there free liquid NO Material wet or dee dry			
SAMPLER'S NAME (print)	(signature)	(date)	
M DA gotto	M DAgostino	1-20-92	
RECORDER'S NAME (print)	(signature)	(date)	
Brack Bounds 1	Goodley & Bounds	1/20/92	

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57 November 10, 1991

November 10, 1991 Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. :	P-748-02410		
SOURCE: TENT No. : PAD No. : 752		DATE No. : 1/20/92 TIME No. :	
BOX LABEL INFORMATION :	748-02410 Heeven 130	ate ?-10-87	
SAMPLE METHOD:	SMAPLE D	ESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SEM SLUI	ID I SOLID (PLASTIC) DGE ER :	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) tan (light brown) solid but chumbied at fouch have a social condition doe to examine of the well. some flaking, material has no enoisting. Penetronetry tests (5) 1.0,0.5, 1.25, 175, 0 Do voids exist? NO			
To there free liquid NO material wet or dry voney dry			
SAMFLER'S NAME (print)	(signature	e) (da:	e)
Mark and	Man Codel	1/20/	92
RECORDER'S NAME (print)	(signature	,	e)
Bradley Bounds	Bradles & De	Boundo 1/20/	92

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57 November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC.			
SAMPLE DATA SHEET 1			
PONDCRETE A	MAILKIAL		
SAMPLE IDENTIFICATION No. : P-80	4-030/8		
SOURCE: TENT No. : 5+ PAD No. :	DATE No. : 1/20/92 TIME No. :		
BOX LABEL INFORMATION : 10/A	Accum date 5-28-67		
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Inght gray, soled, No voids material bricken OFF into chunks sold he broken who half with the use of two hawds Could be broken who half with the use of two hawds Penetrometry tests (5) 4.5, 4.5, 4.0, 4.0 Do voids exist? NO Tes they free liquid no			
Material wet or dry, dry			
SAMPLER'S NAME (print)	(signature) (date)		
M DAGOSTINO M	1 DM got 1/20/92		
RECORDER'S NAME (print)	(signature) (date)		
Bradley Bounds Bia	My Bamai 1/20/92		

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57

November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P- 4		
SOURCE: TENT No. : 8 51 PAD No. : 704	DATE NO. :	1/20/92
BOX LABEL INFORMATION : Accus	1 dati 12-36-86	
SAMPLE METHOD:	SMAPLE DESCRIPTION	: .
DRILL THE MINER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLAS SLUDGE OTHER : <u>Clay</u> /	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) gray in color clay like texture up voids bound. Material can be broke in half but can not be smashed in hand. Penetropetry tests (5) 4.5, 2.75, 30, 2.0, 3.0 Do voids exist? NO Ts there from liquid NO Material wet or dry some moistone (little to nove)		
SAMPLER'S NAME (print)	(signature)	(date)
Mark Addir's -	pak Calar	1-20-92
RECORDER'S NAME (print)	(signature)	(date)
Brad Bounds Die	addry & Bund	1/20/92

Procedure No.:

212B, Rev 0, Draft D

49 of 57

Category 3

DRAFI

Page: Effective Date: Proposed:

November 10, 1991 Waste Operations

Organization:

EG&G ROCKY FLATS, INC.		
SAMPLE DATA SHEET 1		
PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-	03037 ——————————————————————————————————	
SOURCE: TENT No. : PAD No. : 750	DATE No.	: 1/20/92 :
BOX LABEL INFORMATION : Acco	un date 5-22-87	
SAMPLE METHOD:	SMAPLE DESCRIPTION	V : .
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLA SLUDGE OTHER : <u>clay</u> 1	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Alay in color day like fexture some moistire no file (iguid soft enough to get homening sample with chisel to spoons. Penetroneter tests (5) 3,5,30,30,30,30		
To voids exist? NO To there free liquid NO Material wet or due some moisture		
SAMPLER'S NAME (print)	(signature)	(date)
Mark Addis J	Hall Cold	1/20/02
RECORDER'S NAME (print)	(signature)	(date)
Brad Bounds Br	adley Bounds	1/20/92

EG&G ROCKY FLATS PLANT

WR&S Operating Procedures

Procedure No.:

212B, Rev 0, Draft D

Page:

Effective Date: Proposed:

49 of 57 November 10, 1991 Waste Operations

Category 3

DRAFI

Organization:

EG&G ROCKY FLATS, ING.		
SAMPLE DATA SHEET 1		
PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-0		
SOURCE: TENT No. : 7 51 PAD No. : 714	SALTCRETE ALT H DATE No.: 12-11-88 TIME No.:	
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID & & SEMI SOLID (PLASTIC) \(\text{D} \) SEMI SOLID (PLASTIC) \(\text{D} \) OTHER: \(
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Single (w/ inh the Science) Material Same Source (1996) Penetroneter tests (F) 510 All ground Do voids exist? No Ts there free liquid No Material wet or dry Dry		
SAMPLER'S NAME (print)	(signature) (date)	
RICHARD WILLIAM FERPLANDE 1-20-92		
RECORDER'S NAME (print) (signature) (date)		
STEVEN G DAVIS L	teny Dami 1-20-92	

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57 November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC.		
SAMPLE DATA SHEET 1		
PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-038		
SOURCE: TENT No. : 8 54 PAD No. : -704	DATE No. : 5-13-85/	
BOX LABEL INFORMATION :		-
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	_
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.)		
Penetroneter tests (5) 3,5 center 2.0,10 1.5 2.0 Po voids exist? No Ts there free liquid No Material wet or dry Damp		
SAMPLER'S NAME (print)	(date)	
Richard Williams Jet	1-20-92	-
RECORDER'S NAME (print)	(signature) (date)	
STEVE LAVIS I	min & Jan 1-2092	_

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57 November 10, 1991

November 10, 1991 Waste Operations

EG&G ROCKY FLAIS, INC.		
SAMPLE DATA SHEET 1 PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P- 0		
SOURCE: TENT No. : 6 5- PAD No. : 104	DATE No. : 5-19 88 TIME No. :	
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) White aray of particulation Som lair subbles on surface Penetroneter test, (5) 5,0 + All		
To voids exist? No To they free liquid No Material wet or dow Dry		
SAMPLER'S NAME (print)	(signature) (date)	
Bichard latitions Siele	1-20-92	
RECORDER'S NAME (print)	(signature) (date)	
STEVE DAVIS	Leven J Jan 1-20-32	



Category 3

50-39408-7

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B, Rev 0, Draft D 49 of 57 November 10, 1991

Waste Operations

EG&G ROCKY FLATS, INC.		
SAMPLE DATA SHEET 1		
PONDCRETE A	MATERIAL	
SAMPLE IDENTIFICATION No. : P-0	4381	
SOURCE: TENT No. : 8 61	## C DATE No. : 10-4-88 TIME No. :	
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL US SHEBLY TUBE SHOVEL US	SOLID Ø SEMI SOLID (PLASTIC) □ SLUDGE □ OTHER:	
Do voids exist? Ab Ts there from liquid No		
Material wet or dry DAMP (
SAMPLER'S NAME (print)	(signature) (date)	
Richard Williams the	1-20.92	
RECORDER'S NAME (print)	(signature) (date)	
STEVE DAVIS	Leven & Pari 1-20-92	

Procedure No.:

212B, Rev 0, Draft D

Page:

49 of 57

Effective Date: Proposed: Organization:

November 10, 1991 Waste Operations

Category 3

DRAFI

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P- C	23882 Selt.	crete
SOURCE: TENT No. : 8 59		<u>5-18</u> . 58
BOX LABEL INFORMATION :		
SAMPLE METHOD: DRILL HAMMER & CHISEL SHESLY TUBE SHOVEL	SMAPLE DESCRIPTION SOLID SEMI SOLID (PLAS SLUDGE OTHER:	Æ
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Gray Penetrometer tests (5) 5,0 - Very solid Do voids exist? No		
To their free liquid 10 Material wet or dry Dry		
SAMPLER'S NAME (print)	(signature)	(date)
Richard Williams		-23.97
RECORDER'S NAME (print)	(signoture)	(date)
STEVEN DAVIS A	tever & Van	1-2092

(4) SC-41408-M-D

SAMPLE DATA SHEET 1

EG&G ROCKY FLATS, INC.		
SAMPLE DATA SHEET 1		
PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-	04099	
SOURCE: TENT No. : B PAD No. : 104	DATE No. : 01-06-87 TIME No. :	
BOX LABEL INFORMATION :7	43-04099	
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) 04099 VERY HAFD, WITTEE TEXTURE - CRACKING AND GRUMBLING AS SHELBY TUBE HAMMERED IN		
-04099 used for desplicate and 11 gal extraction		
Princtionater tests (F) 4.0, 74.5, 74.5, 74.5, 74.5		
	ELIQUIDS VERY LITTLE MOISTURE	
SAMPLER'S NAME (print)	(signature) (date)	
R.J. APPUGLISE	01/21/92	
51608		
RECORDER'S NAME (print)	(signature) (date)	
K.M. JOHNSON &	outly Janson 01/21/92	

(G2) SC-424XX-T


516337

SAMPLE DATA SHEET 1

EG&G ROCKY FLATS, INC.		
SAMPLE DATA SHEET 1 PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-6		
	tack - DATE No. : 10/8/88	
PAD No. : 904	TME No. :	
BOX LABEL INFORMATION : 743-	04440	
	CLARIE DESCRIPTON	
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
ORILL GHISEL X	SOLID SEMI SOLID (PLASTIC)	
HAMMER & CHISEL X SHEBLY TUBE X SHOVEL X	SLUDGE OTHER:	
REMARKS: (e.g. COLOR, TEXTURE, No	D. OF GRABS, MONITOR READINGS, etc.)	
MED GREV COLOR EG. 1	RICENENT LINER NEAR	
MATERIAL SLIGHTLY E /RUST COLOR)	RITIE AND DISCOLORED	
Penetrometer tests (5) 3.0, 3.0, 2.0, 3.5, 3.5		
Do voids exist? NO		
Material wet or dux SUGHTLY DAMP		
SAMPLER'S NAME (print)	(signature) (date)	
RAPPULGISE €	1/21/92	
516100	1/21/12	
RECORDER'S NAME (print)	(signature) (date)	
K.M. JOHNSON KO	tempor 1/21/92	

SAMPLE DATA SHEET 1

EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1		
PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : P-7	287 Bilting	
SOURCE: TENT No. : 750 51	1115 DATE No. : 6-7-88 1115 TIME No. :	
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION:	
SAMPLE METHOD: DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) TOTAL CONTROL OF THE PROPERTY OF THE PRO		
SAMPLER'S NAME (print) PICK (N.4,AMS Ja	(signature) (cate)	
RECORDER'S NAME (print) STEVE PAVIS	1 (signature) (date) 1	



EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:


Effective Date: Proposed:

Organization:

212B. Rev 0, Draft D 49 of 57

November 10, 1991 Waste Operations


EG&G ROCKY F SAMPLE DATA PONDCRETE N	SHEET 1
SAMPLE IDENTIFICATION No. : P-30	393
SOURCE: TENT No. : _ : _ NO.	DATE No. :
BOX LABEL INFORMATION :	
SAMPLE METHOD:	SMAPLE DESCRIPTION :
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL SPOON	SOLID SEMI SOLID (FLASTIC) SLUDGE OTHER:
light gray white 30	of GRABS. MONITOR READINGS, etc.) and texture throughout y soft throughout
SAMPLER'S NAME (print)	(algnature) (date)
RICHARD WILLIAMS SE	Mille 1492
RECORDER'S NAME (print) STEVEN PAUS	7 (signature) (date)



}	Y FLATS, ING. ATA SHEET 1	
PONDCRET	E MATERIAL	
SAMPLE IDENTIFICATION No. : P-	- PC804 - 776-A-5	540
SOURCE: TENT No.: N/A PAD No.:	Stack MA DATE No.	6-29-89
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION	DN :
ORILL HAMMER & CHISEL SHEBLY TUBE	SOLIO SEMI SOLID (PL SLUDGE OTHER :	ASTIC)
REMARKS: (e.g. COLOR, TEXTURE, Nory Mumbly, grayish 16 Penetronetry tests (5) My > 4.6 Do voids exist? NO To they free liquid NO	110r	AUINGS, etc.)
SAMPLER'S NAME (print)	(signature)	(date)
TERRENCE E. HEALY	Tuna E- Leary	1-27-92
RECORDER'S NAME (print)	(signature)	(date)
TaJuan R. HARSHALL	1 Duan Marchall	1-27-91

(46) SC-465XX-H

	KY FLATS, ING.	
	ATA SHEET 1	
	TE MATERIAL	
SAMPLE IDENTIFICATION No. : E		
SOURCE: TENT No.: NA Building 374 PAD No.: NA	_ Stack AM DATE No.	12-15-89 Day
BOX LABEL INFORMATION :		
SAMPLE METHOD:	SMAPLE DESCRIPTION) . N
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PL SLUDGE OTHER :	LASTIC) O
REMARKS: (e.g. COLOR, TEXTURE GRANTSh Color, Dry and C Penetroneter tests (5) all y Do voids exist? no Ts there free liquid no Material wet or dry Dil	e. No. OF GRABS, MONITOR RE number bruke in Chun	EADINGS, etc.)
SAMPLER'S NAME (print)	(signoture)	(date)
Steven Tice	Men fen	1-2792
RECORDER'S NAME (print)	(signature)	(date)
Taduan ? MARSHALL	Jalya Wartall	1-27-91



EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Procedure No.: Page:

212B, Rev 0, Draft D 49 of 57

November 10, 1991

Category 3

DRAFI

Effective Date: Proposed:

Organization:

Waste Operations

EG&G ROCKY F	•		
SAMPLE DATA SHEET 1 PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. :	_ HOO Z64 H	alt crate	
	19:02 TIME No. :	<u>4-8.</u> 90	
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION	:	
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLAST SLUDGE OTHER:	ic) [
REMARKS: (e.g. COLOR, TEXTURE, No. GRAW EVEN'Y Color Very hard Piece Breaks into Sol	/ \	VGS, etc.)	
Penetroneter tests (F) 5.0 Do voids exist? No Is there from liquid No Material wet or day DRY	ALL		
SAMPLER'S NAME (print)	(signature)	(date)	
I CJ GOET	Doets -	1-27.97	
RECORDER'S NAME (print)	(signature)	(date)	
STEVE Dans	town Dani	1-27 92	

(48) SC-485XX-H

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Category 3

DRAFI

Procedure No.:

Page:

Effective Date: Proposed:

Organization:

212B. Rev 0, Draft D

49 01 57

November 10, 1991

Waste Operations

EG&G ROCKY	
SAMPLE DATA	
PONDCRETE	
SAMPLE IDENTIFICATION No. : 1-	_ HO 3453 Half crake
- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DATE No. : 4-5-91 TIME No. :
BOX LABEL INFORMATION :	
SAMPLE METHOD:	SMAPLE DESCRIPTION :
ORILL HAMMER & CHISEL SHEBLY TUBE	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:
REMARKS: (e.g. COLOR, TEXTURE, NO White Suffer Gray in terior Juney Herd Inner Softer shell Pentirometer text - 5- Material wet ou duz Dry Do unids exist? Ever waren 7 None	Breaks like punice
SAMPLER'S NAME (print) RICHARD WILLIAMS AGE	(signature) (date)
RECORDER'S NAME (print) STEVE DAYS	(signature) (date)

(49) SC-495XX-H

EG&G ROCKY FLATS PLANT WR&S Operating Procedures

Page:

212B, Rev 0, Draft D 49 of 57

Category 3

DRAFI


Effective Date: Proposed:

Organization:


Procedure No.:

November 10, 1991 Waste Operations

EG&G ROCKY F	FLATS, INC.		
SAMPLE DATA SHEET 1			
PONDCRETE I			
SAMPLE IDENTIFICATION No. : # 0			
SOURCE: (2) JENT No. : 374 5. PAD No. : 750 3			
BOX LABEL INFORMATION : 750	- 374 But 10		
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:		
REMARKS: (e.g. COLOR, TEXTURE, No. solid class-gray (Penalrometer) 5	OF GRABS, MONITOR READINGS, etc.)		
Penetrometer tests (5) 3, 55, Do voids exist? no Ts there free liquid no Material wet or day dry	5, 5		
SAMPLER'S NAME (print)	(signature) (date)		
GATHS GALLANDEZ	5. Mast 1-27-92		
RECORDER'S NAME (print)	(signature) (date)		
DJKING RO	ris Leng 1-27-92		



EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL		
SAMPLE IDENTIFICATION No. : #-00	2198 Half crate Salterete	
SOURCE: TENT No. : 474 16 5	TIME No. 1-27-92 TIME No. 8-20	
BOX LABEL INFORMATION : HOO	198	
SAMPLE METHOD:	SMAPLE DESCRIPTION :	
DRILL HAMMER & CHISEL SHEBLY TUBE	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:	
Penatroniter 5	TO CRUMBLE 5,5	
material wet or dry dry		
SAMPLER'S NAME (print)	(sīgnature) (date)	
oug PRITZER	1-27-92	
RECORDER'S NAME (print) 511010 DJ KING	(signature) (date) Hug 1-27-72	




EG&G ROCKY F	FLATS, INC.		
SAMPLE DATA SHEET 1			
PONDCRETE I	MATERIAL	•	
SAMPLE IDENTIFICATION No. : P-			
SOURCE: TENT No. : Na. 5		10-91	
Building 374 PAD No.: n/a	TIME No. : DE	3 7	
BOX LABEL INFORMATION :			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL 0	SOLID	4	
HAMMER & CHISEL SHEBLY TUBE	SEMI SOLID (PLASTIC) SLUDGE		
SHOVEL	OTHER :		
REMARKS : (e.g. COLOR, TEXȚURE, No	. OF GRABS, MONITOR READINGS.	etc.)	
Dry gray very hard, brea	Ks in Chips		
7 9			
			
Penetroneter tests (5) all > 4.5 Do voids exist?			
75 they free liquid NO			
Material wet or log my			
SAMPLER'S NAME (print)	(signoture) ((date)	
MARK A ADDIS MA	et a Color 1/21	B/9 P .	
filling the state of the state		7	
RECORDER'S NAME (print)	(signoture) ((date)	
TriSuan R. MARSHALL Shull	usarmudall 1-2	8-9 2	

EG&G ROCKY FLATS, ING. SAMPLE DATA SHEET 1				
PONDCRE	ETE MATERIAL			
SAMPLE IDENTIFICATION No. :	P- 776-A-6189			
SOURCE: TENT No.: MA	5+46 AG DATE NO. TIME NO.			
BOX LABEL INFORMATION :				
SAMPLE METHOD:	SMAPLE DESCRIPTIO	N : .		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PL. SLUDGE OTHER :	ASTIC) (I)		
REMARKS: (e.g. COLOR, TEXTUI Grayoh, crumbly but Penetroneter tests (5) all 7 Po voids exist? no Is they free liquid no Material wet or dy. Dry	RE, NO. OF GRABS, MONITOR RE			
SAMPLER'S NAME (print)	(signature)	(date)		
Mark D'Agostino M D'Agostur 1-29-92				
RECORDER'S NAME (print) (signature) (date)				
Ta Lian R MATShall	Schan R Mariali	1-28-92		



	CKY FLATS, ING.	
	DATA SHEET 1 RETE MATERIAL	
SAMPLE IDENTIFICATION No. :		Salferell
SOURCE: 374 TENT No. :	Stack - DATE	No 4 -1-80
BOX LABEL INFORMATION : _		
SAMPLE METHOD:	SMAPLE DESCRI	РПОМ :
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID SLUDGE OTHER	
REMARKS : (e.g. COLOR, TEXT	URE, No. OF GRABS, MONITOR	READINGS, etc.)
Cray, crumbly		
Renetraneter tests (F) all Do voids exist? MO Ts they free liquid. NO. Material wet or day NO.	74.5 Y	
SAMPLER'S NAME (print)	(signature)	(date)
T. HEALY	Janua T. Feals	1-25-92
RECORDER'S NAME (print)	(signature)	(date)
SUSANA ZAMARRON	Susana Jamario	~ 1-28-92



EG&G ROCKY FLATS, INC.				
SAMPLE DATA SHEET 1				
PONDCRETE				
SAMPLE IDENTIFICATION No. : P	400277 Salt C	rete		
SOURCE: TENT No. : 5 274 PAD No. :	TIME No. :			
BOX LABEL INFORMATION :				
SAMPLE METHOD:	SMAPLE DESCRIPTION			
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLAS SLUDGE OTHER:	STIC) D		
REMARKS: (e.g. COLOR, TEXTURE, No	. OF GRABS, MONITOR REAL	DINGS, etc.)		
gey - very Dandy - fine				
Penetroneter tests (5) all gree Do voids exist?	aterihan 4.5	<u> </u>		
To their free liquid no material wet or dry dry				
SAMPLER'S NAME (print)	(signature)	(date)		
S. Rico	Here Kar	1-28-93		
RECORDER'S NAME (print) (signature) (date)				
SUSANA TAMARRON SI	Dara Janarian	1-28-92		

	EG&G ROCKY SAMPLE DA		
	PONDCRETE		•
SAMPLE IDE	NTIFICATION NO. : 🗴	HO 3509 1-	lalfcrate Saltcret
SOURCE:	TENT No. :	· · · · · · · · · · · · · · · · · · ·	No. : 5-9.91
BOX LABEL	INFORMATION :		
SAMPLE ME	THOD:	SMAPLE DESCRIP	TION :
	ER & CHISEL 52- Y Tube 0	SOLID SEMI SOLID SLUDGE OTHER :	(PLASTIC) D
REMARKS: White Gray Chips Renetrometer Do isids Zs there Material is	tests (5) 5 All exist? No free liquid No	thick are porou	lewalk
SAMPLER'S	NAME (print) Fernandez J.	(signature)	(date) - /-2842
peoognen's	S NAME (mint)	(signatura)	(data)
ش	S NAME (print)	(signature) Heven J Dan	(date) 1-28.97

(56) 5C-565 XX-H


EG&G ROCKY FLATS, INC.				
SAMPLE DATA SHEET 1				
PONDCRETE				
SAMPLE IDENTIFICATION No. : P- 1	10 3211 Halfcraft	sattcrete		
PAD No : 750 3	DATE No. :	12.1890		
BOX LABEL INFORMATION :				
SAMPLE METHOD:	SMAPLE DESCRIPTION	:		
DRILL HAMMER & CHISEL SHEBLY TUBE	SOLID SEMI SOLID (PLAS SLUDGE OTHER:	TC)		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Very White on surface is Deep approxi				
ANOTHER Tough on o sample				
Penetroneter tests (5) 5 All Do voids exist? No Ts there free liquid No		-		
Material wet or du DRY				
SAMPLER'S NAME (print)	(signature)	(date)		
DORIS KING	J. Sing	1-28-92		
	,			
RECORDER'S NAME (print)	(signature)	(date)		
Steven Davis	Steven & Dan	1-28-97		

EG&G ROCKY FLATS, INC.				
SAMPLE DATA SHEET 1				
PONDCRETE MATERIAL				
SAMPLE IDENTIFICATION No. : P-2739 Saltorate				
SOURCE: TENT No. : 8 5140 PAD No. : 904 MOC	DATE No. : 3-22-87 TIME No. :			
BOX LABEL INFORMATION :				
SAMPLE METHOD:	SMAPLE DESCRIPTION :			
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL Mistake	SOLID			
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.)				
white Dusty and sand texture				
Penetroneter tests (5) -0- Do voids exist? Plastic Folded creating 5" seep Gaps To their first liquid NO Material wet or due Dry				
SAMPLER'S NAME (print)	(date)			
RICHARD WILLIAMS Falflelle 1-28-92				
RECORDER'S NAME (print)	(signature) (date)			
STEVEN DAVIS	turn & Dans 1-28-97			

EG&G ROCKY F SAMPLE DATA PONDCRETE A	SHEET 1	9		
SAMPLE IDENTIFICATION No. : P-Ze				
SOURCE: TENT No. : 8 51	not 661 DATE No. : 47-87 TIME No. :			
BOX LABEL INFORMATION :				
SAMPLE METHOD:	SMAPLE DESCRIPTION :			
DRILL G HAMMER & CHISEL & SHEBLY TUBE & SHOVEL &	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER:			
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Yellowish Surface Off-white granuals under surface Penetropeter tests (5) 2.5, 2, 5 5 4.0 Do voids exist? Us Tis there free liquid No Material wet or day DRY				
SAMPLER'S NAME (print) Richard Williams	(date) (date) (1-28-97			
RECORDER'S NAME (print)	(signature) (date)			

(59) SC- 595XX M

EG&G ROCKY FLATS, ING.			
SAMPLE DATA SHEET 1 PONDCRETE MATERIAL			
SAMPLE IDENTIFICATION No. : P-			
	TME NO. : 7-21-89		
BOX LABEL INFORMATION: TRIMPIL # 748-03257			
SAMPLE METHOD:	SMAPLE DESCRIPTION :		
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER: SOFF, -		
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) Saml, very soft gray outer color gray is white through the middle, granuale soxil.			
Renetranter tests (5) [45 Diel 10t penetrometer Do voids exist? MO Ts there from liquid 10 Material wet or down Dry			
SAMPLER'S NAME (print)	(signature) (date)		
MARK D'Aguastino N	1) Agritus 1-36-92		
RECORDER'S NAME (print)	(signature) (date)		
To lung D morshall - Joli	in Pm Var shall		



EG&G ROCKY FLATS, INC. SAMPLE DATA SHEET 1 PONDCRETE MATERIAL				
SAMPLE IDENTIFICATION No. : P- MOO424 748-3226				
SOURCE: TENT No.: NO. 5. PAD No.: 750, 200				
BOX LABEL INFORMATION :				
SAMPLE METHOD:	SMAPLE DESCRIPTION :			
DRILL HAMMER & CHISEL SHEBLY TUBE SHOVEL	SOLID SEMI SOLID (PLASTIC) SLUDGE OTHER: SOFT -			
REMARKS: (e.g. COLOR, TEXTURE, No. OF GRABS, MONITOR READINGS, etc.) AMUJISH White Sexture four Jupit Texture fout Moist Penetropheter tests (r) .35, .35, .00, 1.0, 1.5 Po voids exist? MO. Ts they free liquid NO Material wet or dow MOIST				
SAMPLER'S NAME (print)	(signature) (date)			
MARIC A. ADDIAS	ax G. Call 1-30-92			
RECORDER'S NAME (print)	(signature) (date)			
Tollook MARSHALL Shill	van 27/Mshoel 1-30-91			